

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20009128/QVF3E2
Date: 07/09/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800115749
Claimant Vehicle No :	SGS1238S	Insured Vehicle No :	SKL1534B
Date of Loss:	27/08/2020	Nature of Claim:	TP
		Claim No:	2968489145SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS1238S		
Make & Model:	BMW 520i LED NAV, 2.0 (A)	Engine No:	18055126B48B20A
Reg. Date:	31/01/2018 (Man. Year: 2017)	Chassis No:	WBAJA12070BJ19136
Colour:	Grey	Odometer:	19182 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/08/2020	
Date Inspected:	31/08/2020	Inspected At:
		Eng Soon Painting Services (HQ) BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Dented	0.00 F	*- F
2	1		*FRT RH FENDER	Repair	0.00 F	*- F
3	1		*RH LOWER MOULDING	Repair	0.00 F	*- F
4	2		*RH LOWER MOULDING BRACKET	Broken	0.00 F	*- F
5	1		*FRONT RH WHEEL RIM	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >