

Auto Dynamac

Reg No. : 503936/00J

Service Trading

BLK 3019A UBI ROAD 1 #01-28

SINGAPORE 408713

TELEPHONE : 6745 9702

FACSMILE : 6748 9764

EMAIL : raymond@autodynamac.com

Vehicle No. : SLQ 333 H
Name : Lye Po Leng
Address : Blk 603 Bedok Reservoir Road
#10-552
Singapore 470603

Date : 10-Feb-20
Model : Mercedes Benz CLA180

Serial No.	Descriptions	Amount
1	Lump sum repair costs	\$ 6,600.00

Grand-total : \$ 6,600.00

Dollars : Six Thousand And Six Hundred Only



MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Invoice No 19019-12/MY

Billing Name & Address

Date 10 Feb 2020

Lye Po Leng
Blk 603 Bedok Reservoir Road
#10-552
Singapore 470603

Vehicle No : SLQ 333 H

Model : Mercedes Benz CLA180

Item	Descriptions	Amount S\$
1	Date of inspection : <u>27 Dec 2019</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>71</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 721.00</u>
	SDLS : SEVEN HUNDRED AND TWENTY-ONE ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



E & O. E



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : **TP / 19019-12/MY / 2019**
Date of Report : **10 Feb 2020**

Lye Po Leng
Blk 603 Bedok Reservoir Road
#10-552
Singapore 470603

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 4 Dec 2019

Workshop Address : Auto Dynamac Service Trading
Blk 3019A Ubi Road 1
#01-28
Singapore 408713

As per your instruction dated **27 Dec 2019** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SLQ 333 H**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SLQ 333 H	Engine No	: 27091031229353
Model	: Mercedes Benz CLA180	Mileage	: 37389
Year / Capacity	: 2017/1595	Colour	: White
Chassis No	: WDD1179422N485805		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 235/35 R7	Continental	6.00	mm	Sport
REAR O/S	: 235/35 R7	Continental	6.00	mm	Sport
FRONT N/S	: 235/35 R7	Continental	6.00	mm	Sport
REAR N/S	: 235/35 R7	Continental	6.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front n/s portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 4 working days to complete.
5. Enclosed number of photograph : 71 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SLQ 333 H**
 Report No: **TP/19019-12/MY / 2019**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
1	Front headlamp	Damage	\$ 2470.00	\$ 2470.00
1	Front bumper	Damage	\$ 1338.00	\$ 1338.00
1	Front bumper sensor	Damage	\$ 165.00	\$ 165.00
1	Front fender	Damage	\$ 585.00	\$ 585.00
1	Front shock absorber	Intact	\$ 658.00	\$
1	Front knuckle arm	Intact	\$ 820.00	\$
1	Front lower arm	Intact	\$ 495.00	\$
1	Front n/s door side mirror	Damage	\$ 1025.00	\$ 1025.00
			<u>\$ 7556.00</u>	<u>\$ 5583.00</u>
<u>Special Nett Items</u>				
1	Front tyre (Depreciation)	Damage	\$ 450.00	\$ 270.00
1	Front sport rim	Damage	\$ 1200.00	\$ 1200.00
			<u>\$ 1650.00</u>	<u>\$ 1470.00</u>

Spare Parts Total \$ 9206.00 \$ 7053.00

Vehicle No: **SLQ 333 H**
Report No: **TP/ 19019-12/MY / 2019**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 9206.00	\$ 7053.00
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 55.00	\$ 40.00
2	To remove and refit front undercarriage.	\$ 380.00	Not Required
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 200.00	\$ 120.00
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 880.00	\$ 500.00
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 800.00	\$ 500.00
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 30.00
Total		<u>\$ 11621.00</u>	<u>\$ 8243.00</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 6600.00

SDLS: SIX THOUSAND SIX HUNDRED ONLY


Qualified Appraiser















































