



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 333H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP (N)	SERVICEABLE	2,470.00	-
1	FRONT BUMPER (N)	TO REPAIR SEE LABOUR	1,338.00	-
1	FRONT BUMPER SENSOR (N)	SERVICEABLE	165.00	-
1	FRONT FENDER (N)	TO REPAIR SEE LABOUR	585.00	-
1	FRONT SHOCK ABSORBER (N)	SERVICEABLE	658.00	-
1	FRONT KNUCKLE ARM (N)	SERVICEABLE	820.00	-
1	FRONT LOWER ARM (N)	SERVICEABLE	495.00	-
1	FRONT N/S DOOR SIDE MIRROR (N)	TO REPAIR SEE LABOUR	1,025.00	-
			7,556.00	-
<u>SPECIAL NETT ITEMS</u>				
1	FRONT TYRE (SN)	SERVICEABLE	450.00	-
1	FRONT SPORT RIM (SN)	CUT	1,200.00	800.00
			1,650.00	800.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.	NOT NECESSARY	55.00	-
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.		200.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT FENDER AND FRONT N/S DOOR SIDE MIRROR.		880.00	300.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		800.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	NOT NECESSARY	100.00	-
			2,415.00	760.00
GRAND TOTAL			11,621.00	1,560.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS3/AIG19022263/Gsf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.