



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG19022263/Gsf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

Date : 03-09-2020



ATTN : LEE MING YAO

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 3033A	Veh. Inspected	SLQ 333H
Policy No.	1700094795	Coverage (\$)	0.00
Claim No.	6437068666SG	Excess (\$)	0.00
Assign From	LEE MING YAO	Assign Date	18/12/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD1179422N485805	Colour	WHITE
Odometer	37024	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/35Z R19	CONTINENTAL	5 mm
L/H Front Tyre	235/35Z R19	CONTINENTAL	5 mm
R/H Rear Tyre	235/35Z R19	CONTINENTAL	5 mm
L/H Rear Tyre	235/35Z R19	CONTINENTAL	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/12/2019	Inspection Date	20/12/2019
Survey held at	AUTO DYNAMAC SERVICE TRADING BLK 3019A #01-28 UBI RD 1 SINGAPORE 408713		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-----------------------