



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG19011439/R1sf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

Date : 16-10-2020



ATTN : NORSIAH MD NOOR

Code : AIG

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLU 9359D	<b>Veh. Inspected</b>	SJH 5465Z
<b>Policy No.</b>	1800016612	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	0858656789SG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	Norsiah Md Noor	<b>Assign Date</b>	30/08/2020

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA AIRWAVE 1.5M A	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008
<b>Chassis No.</b>	GJ11300893	<b>Colour</b>	GREY
<b>Odometer</b>	262323	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

#### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/60 R15	TOYO	6 mm
<b>L/H Front Tyre</b>	195/60 R15	TOYO	6 mm
<b>R/H Rear Tyre</b>	195/60 R15	TOYO	6 mm
<b>L/H Rear Tyre</b>	195/60 R15	TOYO	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

<b>Accident Date</b>	25/06/2019	<b>Inspection Date</b>	27/06/2019
<b>Survey held at</b>	AKA AUTO-25 KAKI BUKIT ROAD 4 SYNERGY @ KB #05-36		
<b>Repairer</b>	-		

#### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>12 Working Days</b>
--	------------------------