

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20009162/GQF3E2

Date: 08/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800042163
Claimant Vehicle No : SGZ76L	Insured Vehicle No : SJX9133X
Date of Loss: 27/08/2020	Nature of Claim: TP Claim No: 5905216335SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ76L		
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Engine No:	3ZRB784734
Reg. Date:	29/07/2016 (Man. Year: 2016)	Chassis No:	ZSU600078503
Colour:	Black	Odometer:	63446 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R20	Rear Tyre Size:	255/45 R20
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	31/08/2020	
Date Inspected:	01/09/2020 Inspected At:	Gold Autoworks Pte Ltd (HQ) 48 TOH GUAN ROAD EAST, #01-119 ENTERPRISE HUB Singapore 608586
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
5	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
6	1		*REAR END PANEL	Bent	0.00 F	*- F
7	1		*TAILGATE	Buckled	0.00 F	*- F
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
11	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
12	1		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
13	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
14	1		*TAILGATE LAMP	Cracked	0.00 F	*- F
15	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >