

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009164/AVF3Q2

Date: 01/02/2021

REFERENCE

| | | | |
|------------------------------|---|-----------------------------|-----------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSNA00001402000 |
| Claimant Vehicle No : | SJA819G | Insured Vehicle No : | GBB9157M |
| Date of Loss: | 27/08/2020 | Nature of Claim: | TP |
| | | Claim No: | SNM20D203085C02/TOHHS |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No: | SJA819G | Engine No: | R18A1743657 |
| Make & Model: | HONDA STREAM, 1.8 (A) | Chassis No: | RN61038728 |
| Reg. Date: | 27/11/2007 (Man. Year: 2007) | Odometer: | 142387 km |
| Colour: | Silver | | |
| Engine Capacity: | 1799 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 215/50 R17 | Rear Tyre Size: | 215/50 R17 |
| Front Left Side: | Dunlop 6 mm | Rear Left Side: | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 3,364.40 | 1,608.00 | 1,756.40 | 52.21 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,380.00 | 1,550.00 | 830.00 | 34.87 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 5,744.40 | 3,158.00 | 2,586.40 | 45.02 |
| Approved Total (Overridden) (\$\$) | | 2,500.00 | | |
| (\$\$) | 5,744.40 | 2,500.00 | 3,244.40 | 56.48 |
| + GST 7.00/7.00% (\$\$) | 402.11 | 175.00 | 227.11 | 56.48 |
| Nett Amount (\$\$) | 6,146.51 | 2,675.00 | 3,471.51 | 56.48 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 31/08/2020 | |
| Date Inspected: | 02/09/2020 Inspected At: | 23 KAKI BUKIT AVE 4 #03-01,VICOM INSPECTION CENTRE |
| | | Repairer: 1st Autoworks Pte Ltd (HQ) |
| Estimated Period of Repair: | 6.0 days | |

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 01 Feb 2021) |
| Parts: | M1-MPV | HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJA819G) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|------------|------------|
| 1 | 1 | | *RR DOOR RH | Dented | 850.00 FL | *850.00 FL |
| 2 | 1 | | *RR DOOR HINGE UPP RH | Not Necessary | 60.00 FL | *- FL |
| 3 | 1 | | *RR DOOR HINGE LOW RH | Not Necessary | 60.00 FL | *- FL |
| 4 | 1 | | *RR DOOR CHECKER RH- LINK CHECK | Not Necessary | 55.00 FL | *- FL |
| 5 | 1 | | *RR DOOR LOCK RH | Not Necessary | 80.00 FL | *- FL |
| 6 | 1 | | *RR DOOR LOCK CATCHER RH -STRIKER | Not Necessary | 75.00 FL | *- FL |
| 7 | 1 | | *RR DOOR INNER TRIM RH | Not Necessary | 250.00 FL | *- FL |
| 8 | 1 | | *RR DOOR RUBBER BEADING RH-BODY SIDE | Not Necessary | 55.00 FL | *- FL |
| 9 | 1 | | *RR DOOR WEATHER STRIP RH | Necessary | 40.00 FL | *40.00 FL |
| 10 | 1 | | *RR DOOR OUTER HANDLE RH | Repair | 45.00 FL | *- FL |
| 11 | 1 | | *RR DOOR OUTER HANDLE KNOB RH -COVER | Not Necessary | 27.00 FL | *- FL |
| 12 | 1 | | *RR DOOR HANDLE INNER BASE RH -BRACKET | Not Necessary | 33.00 FL | *- FL |
| 13 | 1 | | *RR DOOR BLACK STICKER RH | Necessary | 60.00 FL | *60.00 FL |
| 14 | 1 | | *RR DOOR MOULDING RH | Not Necessary | 63.00 FL | *- FL |
| 15 | 1 | | *RR DOOR GLASS RUNCHANNEL RUBBER BEADING WITH QUARTER GLASS RH | Not Necessary | 280.00 FL | *- FL |
| 16 | 1 | | *RR DOOR POWER WINDOW REGULATOR ASSY RH | Not Necessary | 320.00 FL | *- FL |
| 17 | 1 | | *RR FENDER RH | Dented | 860.00 FL | *860.00 FL |
| 18 | 1 | | *RR BUMPER | Repair | 680.00 FL | *- FL |
| 19 | 1 | | *RHR RIM | Cut | 200.00 FL | *200.00 FL |
| 20 | 1 | | *SET DOOR CLIP | Not Necessary | 40.00 FS | *- FS |
| 21 | 1 | | *SEALANT | Not Necessary | 50.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 4,183.00 | 2,010.00 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 818.60 | 402.00 |
| Total Parts (\$\$) | 3,364.40 | 1,608.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO DISMANTLE /REHEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS | New | 850.00 | 600.00 |
| 2 | CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (RHR DOOR ,RHR FENDER ,REAR BUMPER) | New | 750.00 | 600.00 |
| 3 | TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR | New | 150.00 | 30.00 |
| 4 | TO CONDUCT TRANSFER REAR DOOR MECHANISM TO NEW DOOR PANEL | New | 120.00 | 80.00 |
| 5 | TO CONDUCT 4 WHEEL ALIGNMENT | New | 150.00 | 80.00 |
| 6 | TO REMOVE AND REFIX REAR QUARTER GLASS | New | 60.00 | 40.00 |
| 7 | REMOVE AND REFIT TIRE FROM RIM | New | 50.00 | 40.00 |
| 8 | REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS | New | 250.00 | 80.00 |
| Gross Labour Cost (\$\$) | | | 2,380.00 | 1,550.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >