Oualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0180220

Date of Report

: 16/03/2020

To: Mr Cheok Chee Siah

Date of Assignment : 04/02/2020 Report requested by

: Mr Cheok Chee Siah

C/o. 25 Kaki Bukit Road 4 Synergy@KB #03-31 Singapore 417800

Date of Accident

: 03/02/2020

Date of Inspection

: 04/02/2020

Claim No.

; Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SML2932E

Engine Capacity (cc) : 1318cc

Make & Model

: Honda Jazz

Mileage (km)

: 16494km

Date of Registration

: 14/05/2019

Chassis / Frame No. : JHMGK3850KS214464

Colour

: Red

Engine No.

: L13B14101243

TYRE CONDITION

Front LH : 6 mm Front RH

: 6 mm

Make

: Dunlop

Make

: Dunlop

Rear LH

: 6 mm

Rear RH

: 6 mm

Make

: Dunlop

Make

: Dunlop

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

Serviceable

: Serviceable

Steering Apparent Engine Modification

: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. Orion Autoclinic Pte Ltd

25, Kaki Bukit Road 4, Synergy@KB, #03-31, Singapore 417800

ASSESSMENT

Repairer's Estimate

3,440.00

5,324,48 : \$

Revised Amount

4,303.28 : \$

Less Excess

: \$

: \$

Recommended Reserve

Estimated Normal Period of Repairs : 5 Working Days

(Lump Sum)

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited. Page 1 of 4 Qualified Loss Adjusters And Motor Appraisers
Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No: SML2932E

Report No. : PAS/TP/0180220

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Orion Autoclinic Pte Ltd, 25, Kaki Bukit Road 4, Synergy@KB, #03-31, Singapore 417800.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the RHF portion. (The RHF roadwheel was also affected)

DAMAGES

The bonnet, front bumper, front support panel, RHF fender, RHF apron panel, RHF alloy rim, RH headlamp, front grilles, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$4,303.28.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$3,440.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser





Vehicle No: SML2932E

Report No.: PAS/TP/0180220

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions				Repairer's Our Estimate (S\$) Assessment (S\$)					
9 16 34 35				# 11	W.G.FL						
1	1 pc	Headlamp RH	Defaced/Cracked				\$	585.90	\$	585.90 🗸	
2	l pc	Frt grille base	Loop Broken				\$	277.80	\$	277.80 X SVC	
3	1 pc	Frt grille top moulding	Refit				\$	152.90	\$	185	
4	1 pc	Frt grille emblem (H)	Necessary				\$	24.60	\$	24.60 X SVC	
5	1 pc	Frt grille bottom moulding	Refit				\$	188.40	\$	1625 1636 1636 1636 1636	
6	1 pc	Frt bumper	Dented				\$	620.30	\$	620.30	
7	1 pc	Frt bumper no.plate base	Distorted				\$	62.00	\$	62.00 X SVC	
8	1 pc	Frt bumper tow cover	Cracked				\$	29.00	\$	29.00 🗸	
9	1 2 pcs	Frt bumper side garnish trim R/L	Cracked/Necessary	\$	72.30	1pc	\$	144.60	\$	144.60 7 2.30 ✓	
10	I pc	Frt bumper side grille RH	Cracked				\$	115.60	\$	115.60	
11	1 pc	Frt bumper center grille	Cracked				\$	165.70	\$	165.70	
12	8 pcs	Frt bumper clip	Necessary	\$	3.80		\$	30.40	\$	30.40 🗸	
13	2 pcs	Frt bumper retainer R/L	Necessary	\$	26.20		\$	52.40	\$	52.40	
14	l pc	Frt bumper bracket RH	Dented/Broken				\$	38.20	\$	38.20 🗸	
15	1 pc	Frt bumper reinforcement	Refit				\$	260.20	\$	₩.	
16	1 pc	Frt apron panel RH	Dented/Distorted				\$	324.70	Repair\$	324.70 X	
17	1 pc	Frt fender RH	Dented				\$	452.70	\$	452.70 ✓	
18	l pc	Frt fender shield RH	Torn/Deformed				\$	84.30	\$	84.30 🗸	
19	6 pc	Frt fender shield clip RH	Necessary	\$	3.70		\$	22.20	\$	22.20 🗸	
20	1 pc	Frt alloy rim RH	Dented/Defaced				\$	511.20	SVC \$	511.20 X	
21	1 pc	Bonnet	Dented/Repair					(Refer labour no. 3 & 4)			
22	-	Frt support panel	Dented/Repair					(Refer labour no. 3 & 4)			
		** *					-\$	4,143.10		3,541.60	
				Less D	Discount	: 20%	\$	828.62	20% \$	708.32	
			List	Parts Su	ıb-Total	:	\$	3,314.48	\$	2,833.28	
1	1 set	Fit no.plate (w/bracket)	Broken/Dislodged		S/N	Į	\$	50.00	\$	50.00	
10574	on model.	encontrol control 👢 villabilitati - Nacional distributivo (con 🚱	- Anny and a transfer and an artist of the second and the second a	Nett St	ıb-Total	•	\$	50.00	\$	50.00	
				Par	ts Total	:	\$	3,364.48	- \$	2,883.28	

PAS

Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehic	le No : SML2932E		Report No. : PAS/TP/0180220					
S/No.	Labour Descriptions	4.5	oairer's imate (S\$)	Our Assessment (S\$)				
1	To check electrical system and focus headlamp.	\$	50.00	\$	30.00 ✓			
2	To conduct wheel alignment.	\$	60.00	\$	60.00 🗙			
3	To straighten, repair, realign on affected area and replace damaged parts.	\$	800.00	\$	550.00 500 ✓			
4	To spray painting, blending on affected and adjacent area.	\$	1,000.00	\$	750.00 700			
5	To spray anti-rust coating on new and affected panels.	\$	50.00	\$	30.00 🗸			
	Labour Total :	\$	1,960.00	\$	1,420.00			
	Total (Parts & Labour) :	\$	5,324.48		4,303.28			

For Lump Sum Repairs

5 repair days

The final adjusted Lump Sum contract amount is \$ 3,440.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 5 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

55 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.





















