

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009185/AVF3E2

Date: 09/03/2021

REFERENCE

Insured/Claimant:	LAM PEK YING	Policy No:	2100468761		
Date of Loss:	31/08/2020	Nature of Claim:	OD	Claim No:	0295693190SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC8775L		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Engine No:	CZC540605
Reg. Date:	27/05/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8V5G1089776
Colour:	Grey	Odometer:	109608 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$67,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,655.00	10,317.28	7,337.72	41.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,144.00	7,944.00	6,200.00	43.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,799.00	18,261.28	13,537.72	42.57
+ GST 7.00/7.00% (S\$)	2,225.93	1,278.29	947.64	42.57
Nett Amount (S\$)	34,024.93	19,539.57	14,485.36	42.57

INSPECTION

Date of Assignment:	31/08/2020		
Date Inspected:	01/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER COVER TRIM - LH	Not Necessary	161.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	161.00 FS	*- FS
5	4		*FRONT BUMPER PULL STRAP - LOWER	Not Necessary	204.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	38.00 FS	*30.16 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	108.00 FS	*86.00 FS
8	1		*RADIATOR GRILLE	Not Necessary	683.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER	Not Necessary	97.00 FS	*- FS
10	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
11	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
12	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Bent	715.00 FS	*571.60 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	136.00 FS	*108.40 FS
14	1		*FOAM FILLER PIECE COVER	Not Necessary	55.00 FS	*- FS
15	1		*SIGNAL HORN - LH LOW TONE	Damaged	197.00 FS	*157.60 FS
16	1		*FRONT FENDER - LH	Distorted	841.00 FS	*672.80 FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - LH	Bent	27.00 FS	*21.52 FS
19	1		*FRONT FENDER BRACKET	Bent	38.00 FS	*30.40 FS
20	1		*FRONT FENDER BRACE	Bent	95.00 FS	*75.68 FS
21	1		*WHEEL HOUSING LINER SEAL - LH UPPER	Not Necessary	34.00 FS	*- FS
22	1		*WHEEL HOUSING LINER - LH	Deformed	167.00 FS	*133.20 FS
23	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
24	1		*BONNET	Dented	3,134.00 FS	*2,507.20 FS
25	1		*BONNET ATTACHMENT PARTS	Not Necessary	163.00 FS	*- FS
26	2		*BONNET LID HINGE - LH / RH	Not Necessary	122.00 FS	*- FS
27	1		*BONNET CATCH HOOK	Not Necessary	89.00 FS	*- FS
28	1		*BONNET STRIKER	Not Necessary	109.00 FS	*- FS
29	1		*BONNET EDGE PROTECTION - FRONT	Necessary	28.00 FS	*21.84 FS
30	2		*BONNET COVER - LH	Not Necessary	41.00 FS	*- FS
31	1		*BONNET LID LOCK	Not Necessary	212.00 FS	*- FS
32	1		*BONNET SOUND ABSORBER	Not Necessary	217.00 FS	*- FS
33	2		*HEADLIGHT - LH	Smashed	1,969.00 FS	*1,575.20 FS
34	1		*DAY DRIVING LIGHTS POWER MODULE	Cracked	540.00 FS	*431.60 FS
35	1		*GAS DISCHARGE LAMP CONTROL UNIT	Cracked	1,084.00 FS	*867.20 FS
36	2		*GAS DISCHARGE LAMP	Damaged	408.00 FS	*326.40 FS
37	1		*HEADLIGHT HOSE - LH	Not Necessary	51.00 FS	*- FS
38	1		*HEADLAMP HOUSING REPAIR KIT	Not Necessary	130.00 FS	*- FS
39	1		*HEADLAMP HOUSING REPAIR KIT - REAR INNER	Not Necessary	130.00 FS	*- FS
40	1		*LIFT CYLINDER - LH	Cracked	190.00 FS	*152.00 FS
41	1		*LIFT CYLINDER HOSE	Not Necessary	175.00 FS	*- FS
42	1		*WASH WATER RESERVOIR	Deformed	202.00 FS	*161.20 FS
43	1		*LOCK CARRIER	Cracked	719.00 FS	*575.20 FS
44	1		*AIRCON CONDENSER	Not Necessary	517.00 FS	*- FS
45	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	18.00 FS	*- FS
46	1		*READY MIX COOLANT	Not Necessary	91.00 FS	-
47	1		*RADIATOR AIR GUIDE - LH	Not Necessary	24.00 FS	*- FS
48	1		*WATER DEFLECTOR STRIP - LH	Necessary	92.00 FS	*72.32 FS
49	1		*FRONT WINDOW SLOT SEAL - LH	Not Necessary	305.00 FS	*- FS
50	1		*WINDOW GUIDE TRIM STRIP - LH	Not Necessary	254.00 FS	*- FS
51	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*SUNDRIES	Necessary	350.00 FS	*53.36 FS
53	1		*WINDSCREEN WASHER PUMP (Supplementary)	Damaged	121.00 FS	*96.80 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	17,655.00 10,317.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
4	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	350.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	2,750.00
6	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR AND LHS UPPER A-PILLAR	New	4,700.00	2,200.00
7	TO TOW BACK VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
8	TO CARRY OUT PRE-DIAGNOSTIC CHECK AND POST-DIAGNOSTIC CHECK	New	384.00	384.00
9	TO REPAIR LHS FRONT FENDER TOP SUPPORT. (Supplementary)	New	700.00	250.00
10	TO RESPRAY LHS FRONT FENDER TOP SUPPORT. (Supplementary)	New	1,000.00	350.00
Gross Labour Cost (\$\$)			14,144.00	7,944.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >