

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 2049M

| Qty | Description of Parts                                 | Condition                   | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-----------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS                                 |                             |                               |                   |
| 1   | TAILGATE (CONSISTENT)                                | BADLY DENTED                | 1,150.00                      | 955.00            |
| 1   | TAILGATE REAR LOGO (CONSISTENT)                      | NECESSARY                   | 60.00                         | 60.00             |
| 1   | TAILGATE INNER LOCK (CONSISTENT)                     | TWISTED /<br>SHORTED        | 250.00                        | 109.00            |
| 1   | TAILGATE WEATHERSTRIP (CONSISTENT)                   | TWISTED                     | 299.00                        | 199.00            |
| 1   | TAILGATE INNER TRIM (CONSISTENT)                     | DEFORMED /<br>TWISTED       | 298.00                        | 285.00            |
| 1   | SET TAILGATE INNER TRIM CLIPS (CONSISTENT)           | NECESSARY                   | 50.00                         | 50.00             |
| 1   | REAR BUMPER (CONSISTENT)                             | DISTORTED                   | 880.00                        | 650.00            |
| 1   | REAR BUMPER SIDE RETAINER N/S (CONSISTENT)           | CRACKED                     | 60.00                         | 45.00             |
| 1   | SET REAR BUMPER CLIPS (CONSISTENT)                   | NECESSARY                   | 50.00                         | 40.00             |
| 1   | REAR BUMPER BRACKET N/S (CONSISTENT)                 | BENT                        | 110.00                        | 90.00             |
| 1   | REAR BUMPER SPLASH SHIELD N/S (CONSISTENT)           | TORN                        | 241.00                        | 166.00            |
| 1   | SET REAR BUMPER SPLASH SHIELD CLIPS N/S (CONSISTENT) | NECESSARY                   | 50.00                         | 35.00             |
| 1   | REAR END PANEL OUTER (CONSISTENT)                    | BADLY DENTED                | 699.00                        | 545.00            |
| 1   | REAR END PANEL INNER (CONSISTENT)                    | TO REPAIR SEE<br>LABOUR     | 665.00                        | -                 |
| 1   | REAR END PANEL AIR VENT (CONSISTENT)                 | CRACKED                     | 102.00                        | 102.00            |
| 1   | REAR BODY PANEL OUTER N/S (CONSISTENT)               | BADLY DENTED /<br>BUCKLED   | 1,680.00                      | 1,100.00          |
| 1   | REAR BODY PANEL INNER N/S (CONSISTENT)               | TO REPAIR SEE<br>LABOUR     | 1,550.00                      | -                 |
| 2   | TAILLAMPS @\$380.00 (CONSISTENT)                     | N/S BROKEN / O/S<br>CRACKED | 760.00                        | 490.00            |
| 1   | REAR SHOCK ABSORBER N/S (CONSISTENT)                 | TWISTED                     | 255.00                        | 185.00            |
| 1   | REAR AXLE BEAM ASSY (CONSISTENT)                     | BENT                        | 1,685.00                      | 1,200.00          |
| 1   | SLIDING DOOR N/S (CONSISTENT)                        | TO REPAIR SEE<br>LABOUR     | 1,200.00                      | -                 |
| 1   | REAR FLOOR PANEL (CONSISTENT)                        | TO REPAIR SEE<br>LABOUR     | 1,450.00                      | -                 |
|     | LESS 50% DISCOUNT                                    |                             | -                             | -3,153.00         |
|     |  |                             | 13,544.00                     | 3,153.00          |

Report Ref No. CC4/ASM20009201/Upa3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts  | Condition   | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------|-------------------------------|-------------------|
|     | SPECIAL NETT ITEMS  |             |                               |                   |
| 1   | REAR WINDSCREEN SEALANT (SN) (CONSISTENT)   | NECESSARY   | 50.00                         | 40.00             |
| 1   | REAR WINDSCREEN INNER SEAL (SN) (CONSISTENT)  | NECESSARY   | 50.00                         | 30.00             |
| 1   | TAILGATE 70KM/H STICKER (SN) (CONSISTENT)   | NECESSARY   | 20.00                         | 10.00             |
| 1   | SET TAILGATE 'LALAMOVE' STICKER (SN) (CONSISTENT)   | NECESSARY   | 380.00                        | 200.00            |
| 1   | SET REAR BUMPER REVERSE SENSOR (SN)<br>(CONSISTENT)   | SHORTED     | 280.00                        | 200.00            |
| 1   | SET REAR BODY PANEL STICKER N/S (SN)<br>(CONSISTENT)  | NECESSARY   | 380.00                        | 200.00            |
| 1   | REAR BODY PANEL GLASS SEALANT N/S (SN) (CONSISTENT)   | NECESSARY   | 50.00                         | 40.00             |
| 1   | REAR STEEL RIM N/S (SN) (CONSISTENT)  | SERVICEABLE | 100.00                        | -                 |
| 1   | REAR TYRE N/S (SN) (CONSISTENT) (60%)   | сит         | 200.00                        | 120.00            |
|     |   |             | 1,510.00                      | 840.00            |
|     | LABOUR  |             |                               |                   |
|     | TO CHECK WIRING .   |             | 50.00                         | 20.00             |
|     | TO DISMANTLE & REPLACED REVERSE SENSOR .  |             | 80.00                         | 50.00             |
|     | TO DISMANTLE & REFIX REAR WINDSCREEN .  |             | 150.00                        | 100.00            |
|     | TO DISMANTLE & REFIX REAR BODY GLASS N/S .  |             | 150.00                        | 100.00            |
|     | TO TRANSFER TAILGATE MECHANISM .  |             | 100.00                        | 50.00             |
|     | TO DISMANTLE & REPLACED REAR UNDER CARRIAGE.  |             | 380.00                        | 250.00            |
|     | TO CONDUCT WHEEL ALIGNMENT.   |             | 150.00                        | 60.00             |
|     | LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER,REAR BODY PANEL INNER N/S ,SLIDING DOOR N/S AND REAR FLOOR PANEL. |             | 2,800.00                      | 1,400.00          |
|     | TO PUTTY & SPRAY PAINTING.  |             | 2,000.00                      | 1,000.00          |
|     |   |             | -                             | -                 |
|     |   |             | -                             | -                 |
|     |   |             | -                             | -                 |
|     |   |             | 5,860.00                      | 3,030.00          |
|     | GRAND TOTAL   |             | 20,914.00                     | 7,023.00          |

| RECOMMENDED COST OF LUMP SUM REPAIRS |  | 6,400.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |  | ·        |

Report Ref No. CC4/ASM20009201/Upa3q2





Report Ref No. CC4/ASM20009201/Upa3q2

CHUA KANG SENG
Licensed Appraiser