Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20009205/KQF3E2

Date: 11/09/2020

REFERENCE

Date of Loss:

MSIG Insurance (Singapore) Pte. Handling Insurer:

MSD/VMT/20-415634-Policy No:

CA

Claimant Vehicle

SGA7176S

Insured Vehicle No:

FU215R

No:

26/08/2020

Nature of Claim: TP

Claim No:

MSC/V/20-000686

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGA7176S**

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX333024

Reg. Date: 29/11/2005 (Man. Year: 2005) Chassis No: MR053HY4204157018

Colour: Metallic Red Odometer: 340742 km

Engine Capacity: 1497 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

185/65 R14 Front Tyre Size: 185/65 R14 Rear Tyre Size: Front Left Side: Falken 4 mm Rear Left Side: Pirelli 6 mm Falken 4 mm Rear Right Side: Pirelli 6 mm Front Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,267.90	1,245.15	1,022.75	45.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	845.00	1,025.00	54.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,137.90	2,090.15	2,047.75	49.49
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	4,137.90	1,650.00	2,487.90	60.12
+ GST 7.00/7.00% (S\$)	289.65	115.50	174.15	60.12
Nett Amount (S\$)	4,427.55	1,765.50	2,662.05	60.12

INSPECTION

31/08/2020 Date of Assignment:

Date Inspected: 01/09/2020 Inspected At: Yee Auto Pte Ltd (HQ)

160 SIN MING DRIVE, #02-17 SIN MING

AUTOCITY Singapore 575722

Estimated Period of Repair: 4.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 11/9/2020

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 11 Sep 2020)	
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	int Code: (Unsubmitted, no print-code for SGA7176S)		
Validity:	lidity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Mtg Cracked	655.10 F	*399.10 FL
2	1		*FRONT BUMPER SIDE RETAINER - RH	Distorted	62.40 F	*62.40 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1		*HEAD LAMP - RH	Mtg Cracked	711.20 F	*445.00 FL
5	1		*FRONT FENDER - RH	Buckled	498.60 F	*498.60 FL
6	1		*FRONT FENDER DUST COVER RH	Cracked	155.10 F	*155.10 FL
7	1		*SET FRONT FENDER DUST COVER CLIP	Necessary	50.00 F	*50.00 FL
8	1		*FOG LAMP COVER - RH	Serviceable	85.50 F	*- FL
F=Franchise part. L=ListItemDisc. Sub Total (\$\$)		2,267.90 0.00	1,660.20 415.05			
	- List Item Discount on L Items 0.00/25.00% (S\$)			0.00	415.05	
				Total Parts (S\$)	2,267.90	1,245.15

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	<u>Labour Items</u>					
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAWHERE NECESSARY	AT New	800.00	400.00		
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	800.00	400.00		
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL	New	150.00	30.00		
4	TO CHECK WIRING FUNCTIONS	New	120.00	15.00		
	Gross Labo	1,870.00	845.00			
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >