

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009214/EGS3Q2

Date: 12/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100403889

Claimant
Vehicle No : SMF1796U **Insured Vehicle No :** SKR7020X

Date of Loss: 27/08/2020 Nature of Claim: TP Claim No: 0255914997SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF1796U	Engine No:	2ZR0C57455
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU80J034244
Reg. Date:	30/10/2018 (Man. Year: 2018)	Odometer:	129721 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,477.05	2,601.51	5,875.54	69.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,745.00	800.00	1,945.00	70.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,222.05	3,401.51	7,820.54	69.69
Approved Total (Overridden) (\$\$)		2,700.00		
Nett Amount (\$\$)	11,222.05	2,700.00	8,522.05	75.94
+ Loss of Use (5.0 x S\$80.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,107.45		

INSPECTION

Date of Assignment: 31/08/2020

Date Inspected: 01/09/2020 Inspected At:

My Car Consultant Pte Ltd - Ubi (HQ)
53 Ubi Ave 1, #01-33 Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	570.00 FL	*570.00 FL
2	1		*FRONT BUMPER LOGO	Necessary	189.00 FL	*72.00 FL
3	1		*FRONT BUMPER FOGLAMP LH	Not Necessary	435.00 FL	*- FL
4	1		*FRONT BUMPER SIDE LAMP LH	Cut	212.00 FL	*212.00 FL
5	1		*FRONT BUMPER TOP BEAM	Not Necessary	415.00 FL	*- FL
6	1		*FRONT BUMPER LOWER ABSORBER	Not Necessary	235.00 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	186.00 FL	*- FL
8	1		*FRONT BUMPER UNDER GARNISH	Not Necessary	298.00 FL	*- FL
9	2		*FRONT BUMPER SIDE RETAINER	Broken	118.00 FL	*118.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	459.00 FL	*- FL
11	1		*FRONT BUMPER TOWING COVER	Not Necessary	68.00 FL	*- FL
12	1		*FRONT BUMPER SPONGE	Not Necessary	119.00 FL	*- FL
13	1		*FRONT BUMPER LOWER	Not Necessary	415.00 FL	*- FL
14	1		*FRONT FENDER LH	Bent	985.00 FL	*731.35 FL
15	1		*FRONT FENDER EMBLEM HYBRID	Necessary	65.00 FL	*65.00 FL
16	1		*FRONT FENDER INNER COWLING LH	Not Necessary	135.00 FL	*- FL
17	1		*FRONT FENDER GARNISH LH	Not Necessary	64.00 FL	*- FL
18	1		*HEADLAMP LH	Cut	1,487.00 FL	*1,487.00 FL
19	1		*FRONT SUPPORT TOP GARNISH	Not Necessary	289.00 FL	*- FL
20	1		*AIR GUARD LH	Not Necessary	71.00 FL	*- FL
21	1		*FRONT KNUCKLE ARM LH	Not Necessary	821.00 FL	*- FL
22	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	165.00 FL	*- FL
23	1		*FRONT SHOCK ABSORBER LH	Not Necessary	651.00 FL	*- FL
24	1		*FRONT LOWER ARM LH	Not Necessary	628.00 FL	*- FL
25	1		*STABILIZER LINK LH	Not Necessary	198.00 FL	*- FL
26	1		*STEERING TIE ROD LH	Not Necessary	211.40 FL	*- FL
27	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
29	1		*FRONT SPORTS RIM LH	Cut	800.00 FS	*130.00 FS
30	1		*FRONT TYRE LH	Not Necessary	250.00 FS	*- FS
31	1		*FRONT FENDER SEALANT LH	Not Necessary	150.00 FS	*- FS
32	1		*BRAKE FLUID	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,849.40	3,415.35
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,372.35	813.84

Total Parts (\$\$)	8,477.05	2,601.51
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	400.00
2	PANEL BEATING ON AFFECTED AREAS	New	800.00	250.00
3	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
4	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	450.00	0.00
5	REALIGN HEADLAMP	New	120.00	30.00
6	CHECK AND TEST FOR WATER LEAKAGE	New	50.00	0.00
7	CHECK AND RESET FAULT CODE LIGHT ON	New	205.00	0.00
8	CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	30.00
Gross Labour Cost (\$)			2,745.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >