

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20009222/UGA3Q2

Date: 11/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJL6182L	Insured Vehicle No :	SHC8193M
Date of Loss: 29/08/2020	Nature of Claim: TP	Claim No: MCT20080476

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL6182L		
Make & Model:	TOYOTA COROLLA, 1.5 X AXIO (A)	Engine No:	1NZC997896
Reg. Date:	04/12/2008 (Man. Year: 2008)	Chassis No:	NZE1416076547
Colour:	Blue	Odometer:	252486 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,426.48	8,197.99	8,228.49	50.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	3,310.00	430.00	11.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,166.48	11,507.99	8,658.49	42.94
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	20,166.48	9,000.00	11,166.48	55.37
+ Loss of Use (11.0 x S\$50.00/day) (S\$)		550.00		
Nett Liability (S\$)		9,550.00		

INSPECTION

Date of Assignment:	31/08/2020	
Date Inspected:	01/09/2020	Inspected At:
		William Lee Car Air Cond Engrg 61 Ubi Ave 2, Ubi Auto Megamart, #08-04A Singapore 408898
Estimated Period of Repair:	9.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Oct 2020)
Parts:	143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL6182L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	733.80 FL	*733.80 FL
2	1		*FRONT BONNET RUBBER	Necessary	52.60 FL	*52.60 FL
3	2		*FRONT BONNET RUBBER STOPPER	Not Necessary	44.00 FL	*- FL
4	1		*FRONT BONNET LOCK	Twisted	165.50 FL	*165.50 FL
5	1		*FRONT BONNET LOCK CABLE	Not Necessary	82.60 FL	*- FL
6	2		*FRONT BONNET HINGE	Not Necessary	111.20 FL	*- FL
7	1		*FRONT GRILLE	Cracked	335.60 FL	*335.60 FL
8	1		*FRONT GRILLE LOGO	Necessary	68.50 FL	*68.50 FL
9	2		*FRONT HEADLAMP	Cracked	1,616.40 FL	*1,616.40 FL
10	1		*FRONT BUMPER	Distorted	881.95 FL	*655.10 FL
11	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	164.40 FL	*- FL
12	1		*FRONT BUMPER INNER SPONGE	Torn	120.65 FL	*120.65 FL
13	1		*FRONT BUMPER REINFORCEMENT	Distorted	412.50 FL	*412.50 FL
14	2		*FRONT BUMPER REINFORCEMENT STAY	Not Necessary	210.00 FL	*- FL
15	2		*FRONT BUMPER SIDE RETAINER	Bent	128.86 FL	*128.86 FL
16	1		*FRONT BUMPER LOWER STAY	Not Necessary	281.65 FL	*- FL
17	2		*FRONT FENDER	Repair	1,523.60 FL	*- FL
18	1		*FRONT FENDER INNER SHIELD	N/S Deformed	363.24 FL	*181.62 FL
19	2		*FRONT FENDER WHEEL HOUSING	Repair	979.00 FL	*- FL
20	1		*FRONT BRACE PANEL	Twisted	110.50 FL	*110.50 FL
21	1		*FRONT SUPPORT PANEL	Bent / Twisted	1,150.65 FL	*1,150.65 FL
22	2		*ENGINE UNDERCOVER	Not Necessary	205.20 FL	*- FL
23	2		*HORN	Not Necessary	290.00 FL	*- FL
24	1		*AIR CON CONDENSER	Bent / Punctured	1,361.86 FL	*1,361.86 FL
25	1		*AIR CON DISCHARGE PIPE	Not Necessary	311.45 FL	*- FL
26	1		*AIR CON SUCTION PIPE	Not Necessary	301.50 FL	*- FL
27	1		*RADIATOR ASSY	Bent/Punctured	1,626.28 FL	*1,626.28 FL
28	1		*RADIATOR TOP BRACKET	Cracked	179.90 FL	*179.90 FL
29	1		*SET RADIATOR ELECTRIC FAN ASSY	Not Necessary	681.95 FL	*- FL
30	1		*BATTERY BRACKET	Not Necessary	89.60 FL	*- FL
31	1		*REAR BOOT	Repair	1,038.89 FL	*- FL
32	1		*REAR BOOT LOCK	Not Necessary	342.70 FL	*- FL
33	1		*REAR BOOT RUBBER	Not Necessary	192.20 FL	*- FL
34	1		*REAR BOOT LOCK LATCH	Not Necessary	35.89 FL	*- FL
35	1		*REAR BOOT OUTER GARNISH	Not Necessary	280.90 FL	*- FL
36	4		*REAR BOOT RUBBER GUIDE STOPPER	Not Necessary	74.40 FL	*- FL
37	1		*REAR BOOT LOGO	Not Necessary	78.10 FL	*- FL
38	1		*REAR BOOT EMBLEM AXIO	Necessary	74.50 FL	*74.50 FL
39	1		*REAR BOOT EMBLEM X	Necessary	56.90 FL	*56.90 FL
40	2		*REAR BOOT HINGE	Not Necessary	215.00 FL	*- FL
41	1		*REAR BUMPER	Distorted	1,072.20 FL	*681.10 FL
42	1		*REAR BUMPER BRACKET	N/s Dented	189.40 FL	*94.20 FL
43	2		*REAR BUMPER SIDE RETAINER	Not Necessary	145.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR PANEL	Dented/Bent	570.30 FL	*570.30 FL
45	1		*REAR PANEL GARNISH	Not Necessary	170.50 FL	*- FL
46	1		*REAR FLOOR BOARD	Not Necessary	481.95 FL	*- FL
47	2		*TAILLAMP	Not Necessary	918.40 FL	*- FL
48	2		*TAILLAMP LOWER BRACKET	Not Necessary	48.20 FL	*- FL
49	2		*TAILLAMP SEAL	Not Necessary	25.00 FL	*- FL
50	2		*TAILLAMP PANEL	Repair	290.60 FL	*- FL
51	1		*SET FRONT NO PLATE	Bent	50.00 FS	*40.00 FS
52	1		*SET FRONT BUMPER CLIP	Necessary	55.00 FS	*55.00 FS
53	1		*SET REAR BUMPER CLIP	Necessary	55.00 FS	*50.00 FS
54	2		*SETS FRONT FENDER INNER SHIELD CLIP	Not Necessary	86.00 FS	*- FS
55	2		*SETS ENGINE UNDERCOVER CLIP	Not Necessary	68.00 FS	*- FS
56	1		*SET REAR PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
57	1		*SET REAR BOOT INNER TRIM CLIP	Not Necessary	28.00 FS	*- FS
58	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
59	1		*BOT AIR CON OIL	Necessary	60.00 FS	*40.00 FS
60	1		*BOT RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,647.97	10,792.32
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,221.49	2,594.33
Total Parts (\$\$)	16,426.48	8,197.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP	New	100.00	50.00
2	REMOVE,REFIX REVERSE CAMERA & SENSOR	New	100.00	50.00
3	REMOVE,REFIX REAR TRIM & GARNISH	New	100.00	80.00
4	TRANSFER REAR BOOT ATTACHMENT	New	100.00	0.00
5	TO CHECK FRONT & REAR ELECTRICAL WIRING	New	60.00	30.00
6	REMOVE,REFIX A/C CONDENSER & REFILL A/C GAS	New	130.00	100.00
7	TO RESPRAY UNDERCOATING	New	150.00	100.00
8	TO RESPRAY PAINTING & ETC	New	1,500.00	1,500.00
9	PANEL BEATING,REMOVE & REPLACING ABOVE PARTS	New	1,500.00	1,400.00
Gross Labour Cost (\$)			3,740.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >