

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009223/ARA3Q2
Date: 20/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLN1578C	Insured Vehicle No :	GBJ9739S
Date of Loss:	26/08/2020	Nature of Claim:	TP
		Claim No:	8167315767SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1578C	Engine No:	CMS044465
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 (A)	Chassis No:	VEDA02019
Reg. Date:	25/04/2017 (Man. Year: 2016)	Odometer:	40602 km
Colour:	Red		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,004.00	2,708.32	1,295.68	32.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,822.00	1,972.00	1,850.00	48.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,826.00	4,680.32	3,145.68	40.20
+ GST 7.00/7.00% (S\$)	547.82	327.62	220.20	40.20

Nett Amount (S\$)	8,373.82	5,007.94	3,365.88	40.20
		+ Loss of Use (4.0 x S\$60.00/day) (S\$)	240.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	5,255.39	

INSPECTION

Date of Assignment: 28/08/2020

Date Inspected: 28/08/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Dented	2,674.00 F	*2,139.20 F
2	1		*OUTER A-PILLAR DOOR SEAL -RH	Not Necessary	114.00 F	*- F
3	1		*OUTER DOOR SEAL	Necessary	62.00 F	*49.92 F
4	1		*SOUND ABSORBER	Not Necessary	31.00 F	*- F
5	1		*MOUNTING BAR -RH	Not Necessary	239.00 F	*- F
6	1		*EXTERIOR DOOR HANDLE -RH	Cut	337.00 F	*269.60 F
7	1		*DOOR HANDLE CAP -RH	Repair	35.00 F	*- F
8	1		*FRONT DOOR COVER-RH	Cut	163.00 F	*130.40 F
9	1		*REAR PROTECTIVE STRIP -RH	Cut	149.00 F	*119.20 F
10	1		*SUNDRIES	Not Necessary	200.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	4,004.00
						2,708.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	280.00	280.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY RHS FRONT DOOR ,DOOR HANDLE AND RHS REAR FENDER	New	2,300.00	1,000.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,822.00	1,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >