

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC4/AIG20009226/T1ES3Q2

**Date:**

27/09/2021

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900155099

**Claimant Vehicle No :** SHD3016U**Insured Vehicle No :**

SFJ6922B

Date of Loss: 31/08/2020

Nature of Claim:

TP

Claim No:

9529847708SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:

**SHD3016U**

Make &amp; Model:

HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No:

D4FDGU651145

Reg. Date:

24/03/2016 (Man. Year: 2015)

Chassis No:

KMHLB41UMGU086853

Colour:

Blue

Odometer:

660401 km

Engine Capacity:

1685 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

**Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:

205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side:

Hankook 6 mm

Rear Left Side:

Hankook 6 mm

Front Right Side:

Hankook 6 mm

Rear Right Side:

Hankook 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

|                                          | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 4,737.76        | 2,827.84        | 1,909.92        | 40.31        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 1,260.00        | 880.00          | 380.00          | 30.16        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,997.76</b> | <b>3,707.84</b> | <b>2,289.92</b> | <b>38.18</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>2,950.00</b> |                 |              |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| (S\$)                                           | 5,997.76        | 2,950.00        | 3,047.76        | 50.81        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 419.84          | 206.50          | 213.34          | 50.81        |
| <b>Nett Amount (S\$)</b>                        | <b>6,417.60</b> | <b>3,156.50</b> | <b>3,261.10</b> | <b>50.81</b> |
| <b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b> |                 | 150.00          |                 |              |
| <b>+ Car Rental (3.0 x S\$110.67/day) (S\$)</b> |                 | 332.01          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>3,640.51</b> |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                 | <b>3,640.00</b> |                 |              |

INSPECTION

Date of Assignment: 01/09/2020

Date Inspected: 01/09/2020

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
 59 Loyang Drive  
 Singapore 508969

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition     | Repairer's                                                | Amount          |
|-----|-----|----------|--------------------------------|---------------|-----------------------------------------------------------|-----------------|
| 1   | 1   |          | *FRONT BUMPER                  | Torn          | 1,052.20 FL                                               | *1,052.20 FL    |
| 2   | 1   |          | *RAD GRILLE                    | Not Necessary | 1,480.00 FL                                               | *- FL           |
| 3   | 1   |          | *FRONT BUMPER BRACKET RH       | Deformed      | 24.60 FL                                                  | *24.60 FL       |
| 4   | 1   |          | *HEADLAMP RH                   | Cracked       | 1,388.00 FL                                               | *1,388.00 FL    |
| 5   | 1   |          | *HEAD LAMP SUPPORT PANEL       | Not Necessary | 907.40 FL                                                 | *- FL           |
| 6   | 1   |          | *FRONT FENDER SHIELD RH        | Deformed      | 174.90 FL                                                 | *174.90 FL      |
| 7   | 1   |          | *FRONT FENDER RH               | Bent          | 663.00 FL                                                 | *663.00 FL      |
| 8   | 1   |          | *FRONT WHEEL COVER RH          | Cracked       | 107.10 FL                                                 | *107.10 FL      |
| 9   | 1   |          | *FRONT FENDER RH ADVERTISEMENT | Necessary     | 100.00 FS                                                 | *100.00 FS      |
|     |     |          |                                |               | <b>Sub Total (S\$)</b>                                    | <b>5,897.20</b> |
|     |     |          |                                |               | <b>- List Item Discount on L Items 20.00/20.00% (S\$)</b> | <b>1,159.44</b> |
|     |     |          |                                |               | <b>Total Parts (S\$)</b>                                  | <b>4,737.76</b> |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars           | Lab.Type | Repairer's      | Amount        |
|--------------------------------|-----------------------|----------|-----------------|---------------|
| <b><u>Labour Items</u></b>     |                       |          |                 |               |
| 1                              | PANEL BEATING         | New      | 540.00          | 420.00        |
| 2                              | SPRAY PAINTING CHARGE | New      | 480.00          | 400.00        |
| 3                              | REMOVE/REFIX RADIATOR | New      | 90.00           | 0.00          |
| 4                              | TUFF KOTE             | New      | 90.00           | 30.00         |
| 5                              | CHECK LIGHTING        | New      | 60.00           | 30.00         |
| <b>Gross Labour Cost (S\$)</b> |                       |          | <b>1,260.00</b> | <b>880.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >