

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009251/QVF3E2

Date: 30/09/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00005732001
Claimant Vehicle No :	SLG8809C	Insured Vehicle No :	SMG8774G
Date of Loss:	29/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D203130/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG8809C	Engine No:	1ZRY335258
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104558862
Reg. Date:	17/10/2016 (Man. Year: 2016)	Odometer:	174861 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,656.35	5,524.75	4,131.60	42.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,510.00	9,300.00	3,210.00	25.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,166.35	14,824.75	7,341.60	33.12
Approved Total (Overridden) (S\$)		13,000.00		
(S\$)	22,166.35	13,000.00	9,166.35	41.35
+ GST 7.00/7.00% (S\$)	1,551.64	910.00	641.64	41.35
Nett Amount (S\$)	23,717.99	13,910.00	9,807.99	41.35

INSPECTION

Date of Assignment:	04/09/2020	
Date Inspected:	01/09/2020	Inspected At:
		Borneo Motors (S) Pte Ltd (Pandan)
		2 Pandan Crescent
		Singapore 128462
Estimated Period of Repair:	12.0 days	

Adjuster: OI SUN PIN**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG8809C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	2		*SETS SEALANT	Necessary	200.00 FS	*200.00 FS
3	1		*REGN PLATE (PO#) (FRT WITH CASING)	Necessary	80.00 FS	*80.00 FS
4	1		*COVER, FR BUMPER	Crumpled	531.10 FS	*531.10 FS
5	1		*GRILLE, RADIATOR LWR	Serviceable	170.10 FS	*- FS
6	1		*SUPPORT, FR BUMPER RH	Necessary	85.50 FS	*85.50 FS
7	1		*SUPPORT, FR BUMPER LH	Necessary	85.50 FS	*85.50 FS
8	1		*ABSORBER, FR BUMPER	Serviceable	90.10 FS	*- FS
9	1		*REINFORCEMENT, FR	Serviceable	399.50 FS	*- FS
10	2		*CLIP	Necessary	5.00 FS	*5.00 FS
11	1		*GRILLE, RADIATOR	Serviceable	643.00 FS	*- FS
12	1		*SUPPORT SUB-ASSY, HO	Serviceable	149.40 FS	*- FS
13	1		*HEADLAMP ASSY, RH	Serviceable	927.60 FS	*- FS
14	1		*HEADLAMP ASSY, LH	Serviceable	927.60 FS	*- FS
15	1		*COVER, RR BUMPER	Crumpled	556.40 FS	*556.40 FS
16	1		*REINFORCEMENT, RR	Bent	399.50 FS	*399.50 FS
17	1		*RETAINER, RR BUMPER L	Necessary	109.30 FS	*109.30 FS
18	1		*RETAINER, RR BUMPER R	Necessary	109.30 FS	*109.30 FS
19	1		*RETAINER, RR BUMPER R	Necessary	60.40 FS	*60.40 FS
20	1		*RETAINER, RR BUMPER L	Necessary	60.40 FS	*60.40 FS
21	4		*PIECE, RR BUMPER	Necessary	16.40 FS	*16.40 FS
22	1		*PANEL, LAMP LOWER	Dented	670.00 FS	*670.00 FS
23	1		*PANEL SUB-ASSY, LUGG	Dented	793.20 FS	*793.20 FS
24	1		*LOCK ASSY, LUGGAGE	Jammed	399.50 FS	*399.50 FS
25	1		*PLATE, RR FLOOR	Crumpled	241.90 FS	*241.90 FS
26	1		*REAR BOOT LID EMBLEM	Necessary	50.70 FS	*50.70 FS
27	1		*PLATE, LUGGAGE COMPT	Necessary	41.00 FS	*41.00 FS
28	1		*PLATE, LUGGAGE COMPT	Necessary	45.60 FS	*45.60 FS
29	1		*LAMP ASSY, RR COMB RH	Serviceable	379.80 FS	*- FS
30	1		*LAMP ASSY, RR COMBIN LH	Cracked	379.80 FS	*379.80 FS
31	1		*LAMP ASSY, RR, RH	Cracked	394.50 FS	*394.50 FS
32	1		*LAMP ASSY, RR, LH	Serviceable	394.50 FS	*- FS
33	1		*BACK SENSOR (040) 310A	Shorted	159.75 FS	*159.75 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **9,656.35** **5,524.75**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE AND REFOCUS HEADLAMP	New	180.00	180.00
2	RESET AND REPROGRAMME ECU	New	180.00	180.00
3	REMOVE ALL NECESSARY DAMAGED PARTS. TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR	New	2,160.00	1,440.00
4	SPRAY PAINT ON FRT AFFECTED PORTION OF CAR	New	1,770.00	1,180.00
5	CHK REAR WIRING SYSTEM AND CONDUCT WATER LEAK	New	180.00	180.00
6	DRILL HOLE TO INSTALL REVERSE SENSOR	New	180.00	180.00
7	REMOVE BOOT INTERIOR TO ASSIST REPAIR	New	360.00	360.00
8	REMOVE BOOT COMPONENTS TO TRANSFER ONTO NEW BOOT	New	360.00	360.00
9	REMOVE ALL NECESSARY DAMAGED PARTS. TO REPLACE, REPAIR STRAIGHTEN REAR BUMPER, REAR BOOT, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR	New	3,600.00	2,880.00
10	SPRAY PAINT ON REAR AFFECTED PORTION OF CAR	New	3,540.00	2,360.00
Gross Labour Cost (\$\$)			12,510.00	9,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >