



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 2412X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR SIDE PANEL RH (SN)	DENTED	3,800.00	1,600.00
1	REAR SIDE PANEL LOWER PROTECTOR RH (SN)	DENTED	1,200.00	500.00
1	REAR SIDE PANEL INNER PILLAR (SN)	TO REPAIR SEE LABOUR	1,200.00	-
1	REAR SIDE PANEL INNER PANEL (WOODEN) (SN)	NOT NECESSARY	480.00	-
1	REAR SIDE PANEL INNER LOWER SUPPORT (SN)	DENTED	800.00	300.00
1	SIDE END PANEL RH (SN)	TO REPAIR SEE LABOUR	2,800.00	-
2	REAR BOX FLOOR PANEL (WOODEN) @\$1800.00 (SN)	NOT NECESSARY	3,600.00	-
3	REAR BOX CHASSIS MEMBER SUPPORT @\$1400.00 (SN)	CRACKED	4,200.00	600.00
1	SET COMPANY STICKER (SN)	NECESSARY	4,800.00	2,500.00
			22,880.00	5,500.00
	<u>LABOUR</u>			
	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK. INCLUSIVE OF THE REPAIR OF REAR SIDE PANEL INNER PILLAR AND SIDE END PANEL RH.		1,600.00	600.00
	TO PUTTY, SPRAY PAINT, POLISH WAX.		1,600.00	400.00
	WIRING, BULB CHECKING.	NOT NECESSARY	80.00	-
			3,280.00	1,000.00
	GRAND TOTAL		26,160.00	6,500.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			5,200.00
---	--	--	-----------------

Report Ref No. CS/INC20009256/Aqf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.