



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 2222U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CUT	2,512.64	1,614.00
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	98.27	-
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	339.48	-
1	FRONT BUMPER FOG LAMP CHROME GARNISH LH	NOT NECESSARY	210.91	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	313.94	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	553.21	-
1	FRONT HEADLAMP LH	NOT NECESSARY	4,227.52	-
1	FRONT HEADLAMP BRACKET LH	NOT NECESSARY	189.60	-
1	FRONT GRILLE	NOT NECESSARY	1,124.00	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	299.46	-
	LESS 25% DISCOUNT		-2,467.26	-403.50
			7,401.77	1,210.50
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	SERVICEABLE	30.00	-
1	FRONT BUMPER SENSOR (SN)	NOT NECESSARY	440.00	-
1	SET FRONT GRILLE CLIP (SN)	NOT NECESSARY	60.00	-
			530.00	-
	<u>LABOUR</u>			
	CHECK WIRING AND LIGHTNING SYSTEM.	NOT NECESSARY	60.00	-
	PANEL BEATING ON AFFECTED AREAS.		800.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	200.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			1,810.00	400.00
	GRAND TOTAL		9,741.77	1,610.50
	RECOMMENDED COST OF REPAIRS			1,610.50

Report Ref No. CS/SMO20009263/DUqf3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.