

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20009267/EVF3E2
Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2070028714
Claimant Vehicle No : FBE6528E	Insured Vehicle No : SMS3571U
Date of Loss: 08/08/2020	Nature of Claim: TP Claim No: 7416507501SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBE6528E	Engine No:	NCB150E0066888
Make & Model:	HONDA CBR, 150cc 150M (M)	Chassis No:	NCB1500066888
Reg. Date:	12/07/2010 (Man. Year: 2009)	Odometer:	94376 km
Colour:	Blue		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/09/2020	
Date Inspected:	01/09/2020 Inspected At:	Xin Yun Auto Pte Ltd (kaki Bukit) (HQ) 8 Kaki Bukit Avenue 4, #05-23 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRONT RIM	Cut	0.00 F	*- F
3	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
4	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
5	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
6	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
7	1		*FRONT WINDSHIELD	Broken	0.00 F	*- F
8	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
9	1		*ERP UNIT	Cut	0.00 F	*- F
10	1		*HANDLE BAR	Bent	0.00 F	*- F
11	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
12	1		*CLUTCH LEVER	Cut	0.00 F	*- F
13	2		*SIDE FAIRING	Cut	0.00 F	*- F
14	1		*FAIRING TOP GARNISH	Broken	0.00 F	*- F
15	1		*FRONT FOOT REST	Cut	0.00 F	*- F
16	1		*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
17	1		*REAR BOX	Cut	0.00 F	*- F
18	1		*EMBLEM	Necessary	0.00 F	*- F
19	1		*STICKER	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >