

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20009270/ATF3E2

Date: 15/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900015953
Claimant Vehicle No : SLH8290S	Insured Vehicle No : SMH9569X
Date of Loss: 01/07/2020	Nature of Claim: TP Claim No: 6012103519SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH8290S		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Engine No:	G4FGGU275981
Reg. Date:	21/11/2016 (Man. Year: 2016)	Chassis No:	KMHD841CMHU310442
Colour:	Gold	Odometer:	285753 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,562.72	2,870.56	5,692.16	66.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	630.00	3,010.00	82.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,202.72	3,500.56	8,702.16	71.31
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	12,202.72	2,800.00	9,402.72	77.05

INSPECTION

Date of Assignment:	01/09/2020	
Date Inspected:	02/09/2020	Inspected At: Fixmate Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #04-06, PREMIER @ KB SINGAPORE 415875
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	568.20 FL	*568.20 FL
2	2		*FRONT BUMPER SIDE AIR GUIDE	Not Necessary	291.20 FL	*- FL
3	1		*FRONT BUMPER TOP SEAL (RUBBER)	Not Necessary	98.70 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Cracked	186.50 FL	*186.50 FL
5	2		*FRONT BUMPER SIDE RETAINERS	Necessary	172.60 FL	*172.60 FL
6	2		*FRONT BUMPER FRONT BRACKETS	Not Necessary	151.60 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	385.50 FL	*- FL
8	1		*FRONT BUMPER TOWING COVER	Not Necessary	48.20 FL	*- FL
9	2		*FRONT FOGLAMP COVER RH	Not Necessary	312.60 FL	*- FL
10	2		*FRONT FOGLAMP	Not Necessary	651.40 FL	*- FL
11	1		*FRONT ENGINE UNDERCOVER	Not Necessary	286.50 FL	*- FL
12	1		*FRONT HEADLAMPS	O/S Cracked	3,597.00 FL	*1,798.50 FL
13	1		*FRONT HEADLAMP BRACKETS	O/S Cracked	179.40 FL	*89.70 FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	987.50 FL	*- FL
15	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	224.60 FL	*- FL
16	1		*FRONT RADIATOR GRILLE	Cracked	1,298.60 FL	*560.00 FL
17	1		*FRONT NUMBER PLATE GARNISH	Deformed	75.20 FL	*75.20 FL
18	2		*FRONT FENDER INNER COWLING	Not Necessary	291.80 FL	*- FL
19	1		*FRONT WASHER TANK	Not Necessary	168.90 FL	*- FL
20	2		*FRONT WASHER TANK MOTOR	Not Necessary	251.20 FL	*- FL
21	1		*FRONT AIR INTAKE VENT	Not Necessary	188.70 FL	*- FL
22	1		*SET FRONT NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
23	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
24	1		*SET FRONT SUPPORT TOP GARNISH	Not Necessary	30.00 FS	*- FS
25	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*SET FRONT ENGINE UNDERCOVER CLIPS	Not Necessary	30.00 FS	*- FS
27	2		*SETS FRONT FENDER INNER COWLING	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,645.90	3,560.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,083.18	690.14
Total Parts (\$\$)	8,562.72	2,870.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	New	1,600.00	350.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	250.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	0.00
4	TO REMOVE AIR CON CONDENSER AND TOP UP AIR CON GAS	New	120.00	0.00
5	TO REMOVE / REFIT WIRING CHECKS ON FRONT HEADLAMPS	New	120.00	30.00
Gross Labour Cost (\$\$)			3,640.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >