



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5311J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER,REAR BUMPER	SERVICEABLE	485.60	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	22.00	-
1	REINFORCEMENT SUB-ASSY,REAR BUMPER	TO REPAIR SEE LABOUR	332.70	-
1	GUARD,REAR BUMPER,CENTER	DENTED / CUT	374.50	374.50
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	132.60	-
1	REFLECTOR ASSY-REFLEX	SERVICEABLE	39.00	-
1	REAR TAILGATE OUTER GARNISH	SERVICEABLE	913.60	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	372.30	-
1	LENS & BODY,REAR COMBINATION LAMP,NO 2	SERVICEABLE	261.00	-
1	LENS & BODY,REAR COMBINATION LAMP	SERVICEABLE	339.60	-
1	LAMP ASSY,REAR	SERVICEABLE	293.60	-
	LESS 25% DISCOUNT		-891.62	-93.62
			2,674.88	280.88
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	75.00	-
1	REAR TAILGATE TOYOTA LOGO (SN)	NOT NECESSARY	47.90	-
1	REAR TAILGATE WORDING "PRIUS" (SN)	NOT NECESSARY	54.60	-
1	REAR TAILGATE WORDING "HYBRID" (SN)	NOT NECESSARY	54.60	-
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	65.00	-
1	REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	140.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	180.00	-
			1,477.10	-
<u>LABOUR</u>				
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	120.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-

Report Ref No. CC3/TP20009272/Kda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY,REAR BUMPER.		1,200.00	60.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
			2,990.00	180.00
GRAND TOTAL			7,141.98	460.88
RECOMMENDED COST OF REPAIRS				460.88

Report Ref No. CC3/TP20009272/Kda3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.