

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20009281/T1tf3s2					
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 10-09-2020 Code: INC4		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKF 2599P	Veh. Inspected	SHA 7981Y	
	Policy No.	5070144414-04	Coverage (\$)	0.00	
	Claim No.	MT/1101808-002	Excess (\$)	0.00	
	Assign From		Assign Date	31/08/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I40	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	KMHLB41UMGU077463	Colour	BLUE	
	Odometer	721858	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	29/08/2020	Inspection Date	31/08/2020	
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD		
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Estimate Days of Repair

2 Working Days