

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009282/AES3Q2

Date: 26/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800101941
Claimant		
Vehicle No : SLX6520H	Insured Vehicle No :	SKA8161E
Date of Loss: 22/08/2020	Nature of Claim: TP	Claim No: 9020302643SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX6520H		
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Engine No:	2ZR0A16447
Reg. Date:	03/04/2018 (Man. Year: 2017)	Chassis No:	ZVW400026954
Colour:	Black	Odometer:	205233 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Crucero 6 mm	Rear Left Side:	Crucero 6 mm
Front Right Side:	Crucero 6 mm	Rear Right Side:	Crucero 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,094.97	957.17	2,137.80	69.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,430.00	1,700.00	54.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,224.97	2,387.17	3,837.80	61.65
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	6,224.97	1,900.00	4,324.97	69.48
+ GST 7.00/7.00% (S\$)	435.75	133.00	302.75	69.48
Nett Amount (S\$)	6,660.72	2,033.00	4,627.72	69.48
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,382.00		
Global Sum Settlement (S\$)		2,380.00		

INSPECTION

Date of Assignment:	31/08/2020	
Date Inspected:	31/08/2020 Inspected At:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre Singapore 415933
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE SKIRT LH	Cracked	688.90 FL	*688.90 FL
2	1		*REAR DOOR LH	Repair	1,355.90 FL	*- FL
3	1		*REAR BUMPER	Torn	850.20 FL	*489.00 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Necessary	62.40 FL	*45.00 FL
5	1		*REAR FENDER LH	Repair	1,115.90 FL	*- FL
6	1		*SET SIDE SKIRT CLIPS	Necessary	20.00 FS	*20.00 FS
7	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,113.30	1,262.90
- List Item Discount on L Items 25.00/25.00% (\$)	1,018.33	305.73
Total Parts (\$)	3,094.97	957.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,200.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	250.00	50.00
4	WIRING CHECK	New	80.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
6	TO REMOVE AND REFIX REAR DOOR MECHANISM	New	120.00	0.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	60.00	50.00
8	REMOVE AND REFIX REAR QUARTER GLASS	New	120.00	0.00
Gross Labour Cost (\$\$)			3,130.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >