

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4762H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
10	REAR BUMPER COVER CLIPS	NOT NECESSARY	22.00	-
1	REAR FOG LAMP	CRACKED	201.50	201.50
1	REAR BUMPER REINFORCEMENT	CRACKED	294.80	294.80
1	ANTENNA ASSY - SMARTK	CRACKED	689.50	689.50
	LESS 20% DISCOUNT		-423.69	-419.29
			1,694.76	1,677.16
	NETT ITEMS			
1	REAR NO. PLATE (N)	CRACKED	25.00	25.00
1	REVERSE SENSOR ASSY (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-20.50	-20.50
			184.50	184.50
	<u>LABOUR</u>			
	PANEL BEATING.		350.00	320.00
	SPRAY PAINTING.		250.00	200.00
	REMOVE / REFIX REVERSE SENSOR.		100.00	30.00
			700.00	550.00
	GRAND TOTAL		2,579.26	2,411.66

RECOMMENDED COST OF LUMP SUM REPAIRS	1,650.00
(TO ITS PRE-ACCIDENT CONDITION)	
(CONFIRMED)	

Report Ref No. NS/INC20009283/T1qf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.