## **COMFORTDELGRO ENGINEERING PTE LTD**

## **REPAIR ESTIMATE**

DATE:	71.03.7029		3P INSURANCE:	NTUC	
MODEL:	HYUNDIN ICMO		SURVEYOR:	LKK	
VEH NO.:	SHA4762H		MVA:	Hong LT	
PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS	
Sup	Rear Bumper Rear Bumper Centre Moulding Assy Rear Bumper Cover Clips Suff for fay lamp \$201.50.00  Antonia Way - Smith 189450 and SPARE PARTS SUB TOTAL  LESS 20%  DISCOUNTED SPARE PARTS TOTAL  Rear No. Plate LESS 10%  LKK Auto Consultants hence notify the Repairer of the following:  • To resurvey before/after spray painting.	ey fice* basis ed <u>and</u> e Company	180.	\$459.40 \$451.25 \$22.00 \$932.65 \$186.53 <b>\$746.12</b> \$25.00 \$2.50 \$22.50	2096.45 1677.16.
This is an	Panel Beating  Spray Painting  Remove/Refix Reverse Sensor  Taylory 31/6/20 (3)  -2 day  LABOUR TOTAL  He firm of the vegor  Faylor & Hundown  Initial estimate based on a visual inspection of the above after the vehicle is surveyed by a motor Surveyor appoints	vehicle.	The final repair	\$350.00 \$250.00 \$100.00 \$700.00	20 200 50 550. 2411.60 2/5\$/650