

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009289/KGS3Q2
Date: 07/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100309446
Claimant Vehicle No :	SLA2176R	Insured Vehicle No :	SFK933D
Date of Loss:	30/08/2020	Nature of Claim:	TP
		Claim No:	5009311326SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA2176R	Engine No:	8ARZ028529
Make & Model:	LEXUS IS200T, 2.0 EXECUTIVE (A)	Chassis No:	JTHBA1D2805019517
Reg. Date:	25/02/2016 (Man. Year: 2016)	Odometer:	79146 km
Colour:	Metallic Pearl White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,758.78	8,579.13	6,179.65	41.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,550.00	820.00	34.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,128.78	10,129.13	6,999.65	40.86
+ GST 7.00/7.00% (S\$)	1,199.01	709.04	489.97	40.86

Nett Amount (S\$)	18,327.79	10,838.17	7,489.62	40.86
+ Loss of Use (8.0 x S\$90.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,560.17		
Global Sum Settlement (S\$)		11,550.00		

INSPECTION

Date of Assignment: 01/09/2020

Date Inspected: 02/09/2020

Estimated Period of Repair: 5.0 days

Inspected At: K.kim Hin Auto Pte Ltd (Autocity)
160 Sin Ming Drive, #02-18/19/20/21, Sin Ming Autocity
Singapore 575722

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP ASSY (LH/RH)	Serviceable	323.40 FL	*- FL
2	1		*REAR BUMPER -TOP	Bent	1,061.80 FL	*1,061.80 FL
3	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Distorted	290.00 FL	*290.00 FL
4	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
5	1		*REAR BUMPER -BOTTOM	Cracked	503.30 FL	*503.30 FL
6	2		*REAR BUMPER REFLECTOR (LH/RH)	Serviceable	335.60 FL	*- FL
7	4		*REAR BUMPER PARKING SENSOR	Shorted (2 PCS ONLY)	1,963.20 FL	*950.00 FL
8	1		*REAR BUMPER SPONGE	Cracked	112.40 FL	*112.40 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	485.00 FL	*485.00 FL
10	1		*BOOTLID	Bent	1,733.90 FL	*1,450.00 FL
11	2		*BOOTLID HINGES (LH/RH)	Repair	447.40 FL	*- FL
12	2		*BOOTLID HINGES COVER (LH/RH)	Serviceable	201.40 FL	*- FL
13	1		*BOOTLID LOGO	Necessary	71.70 FL	*71.70 FL
14	1		*BOOTLID LEXUS EMBLEM	Necessary	68.20 FL	*68.20 FL
15	1		*BOOTLID IS200T EMBLEM	Necessary	110.00 FL	*110.00 FL
16	1		*BOOTLID WEATHERSTRIP (50%)	Distorted / Cut	214.11 FS	*118.95 FS
17	1		*BOOTLID LOCK	Dented	499.00 FL	*385.40 FL
18	1		*BOOTLID LOCK CATCH	Repair	45.00 FL	*- FL
19	4		*BOOTLID RUBBER STOPPER	Serviceable	60.00 FL	*- FL
20	1		*BOOTLID INNER TRIM	Serviceable	454.80 FL	*- FL
21	10		*BOOTLID INNER TRIM CLIPS	Necessary	55.00 FL	*55.00 FL
22	2		*BOOTLID LAMP (LH/RH)	Mtg Cracked	1,121.00 FL	*901.00 FL
23	1		*BOOTLID OUTER GARNISH	Serviceable	149.70 FL	*- FL
24	2		*BOOTLID OUTER GARNISH LAMP COVER (LH/RH)	Serviceable	323.40 FL	*- FL
25	2		*TAILLAMP ASSY (LH/RH)	Mtg Cracked	1,466.40 FL	*1,361.00 FL
26	2		*TAILLAMP RETAINER (LH/RH)	Necessary	250.80 FL	*250.80 FL
27	1		*REAR END PANEL	Bent	811.90 FL	*780.00 FL
28	1		*REAR END PANEL TOP GARNISH	Buckled	349.70 FL	*349.70 FL
29	1		*SPARE TYRE LOCK SCREW	Cracked	85.90 FL	*85.90 FL
30	1		*SPARE TYRE PANEL TOP BOARD	Serviceable	790.30 FL	*- FL
31	2		*SPARE TYRE PANEL TOP SPONGE COMPARTMENT (LH/RH)	Serviceable	516.00 FL	*- FL
32	2		*SPARE TYRE PANEL TOP SIDE BOARD	Serviceable	575.80 FL	*- FL
33	4		*SPARE TYRE PANEL TOP SIDE BOARD ROPE HOOK	Dented (1 PCS ONLY)	296.00 FL	*74.00 FL
34	1		*REAR FLOOR PANEL UNDERCOVER	Serviceable	503.30 FL	*- FL
35	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	16,370.41
					- List Item Discount on L Items 10.00/10.00% (\$)	1,611.63
					Total Parts (\$)	14,758.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING ,WELDING ALIGN REFIX AND TO RENEW AFFECTED PARTS	New	800.00	600.00
2	TO FOCUS TAILLAMP TO CHECK REAR WIRING AND LIGHTING OPERATION	New	50.00	20.00
3	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING ,ROOF LINING SEATS,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	120.00	60.00
4	TO APPLY UNDERSEALING	New	120.00	60.00
5	TO REMOVE AND REFIT REVERSE SENSOR ASSY	New	80.00	60.00
6	TO PUTTY AND RESPRAY ON AFFECTED PORTION	New	1,200.00	750.00
Gross Labour Cost (S\$)			2,370.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >