

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009290/AQF3Q2

Date: 15/03/2021

REFERENCE

Insured/Claimant:	ONG TAR GIN	Policy No:	2100427526	
Date of Loss:	28/08/2020	Nature of Claim:	OD	Claim No: 6846187708SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV1663J		
Make & Model:	AUDI A4, 1.8 TFSI MU (B8) (A)	Engine No:	CJE108592
Reg. Date:	31/08/2015 (Man. Year: 2015)	Chassis No:	WAUZZZBK8FA160411
Colour:	Bronze	Odometer:	60873 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,742.40	7,918.24	23,824.16	75.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,094.00	3,844.00	8,250.00	68.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,836.40	11,762.24	32,074.16	73.17
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	43,036.40	10,962.24	32,074.16	74.53
+ GST 7.00/7.00% (S\$)	3,012.55	767.36	2,245.19	74.53
Nett Amount (S\$)	46,048.95	11,729.60	34,319.35	74.53

INSPECTION

Date of Assignment:	01/09/2020	
Date Inspected:	01/09/2020	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,278.00 FS	*1,822.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	256.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	225.00 FS	*180.00 FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Deformed	136.00 FS	*106.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	192.00 FS	*- FS
6	1		*FRONT BUMPER SUPPORT ELEMENT - UPPER	Not Necessary	59.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,077.00 FS	*861.60 FS
8	1		*FRONT BUMPER VENT GRILLE - RH	Not Necessary	134.00 FS	*- FS
9	1		*FRONT WHEEL SPOILER - RH	Torn	51.00 FS	*40.16 FS
10	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	870.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
12	1		*FOAM FILLER PIECE COVER	Not Necessary	126.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	36.00 FS	*28.48 FS
14	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
15	1		*AIRCON STICKER	Not Necessary	24.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT	Damaged	25.00 FS	*19.84 FS
17	1		*SIGNAL HORN - LOW TONE RH	Not Necessary	199.00 FS	*- FS
18	1		*SPRING SHACKLE - RH LOW TONE	Not Necessary	24.00 FS	*- FS
19	1		*FRONT FENDER - RH	Distorted	979.00 FS	*782.80 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
21	1		*FRONT FENDER BRACKET - RH FRONT	Bent	52.00 FS	*41.36 FS
22	1		*DEFORMATION ELEMENT BRACKET - RH REAR	Not Necessary	49.00 FS	*- FS
23	1		*FRONT FENDER BRACE - RH LOWER	Bent	117.00 FS	*93.60 FS
24	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	127.00 FS	*- FS
25	1		*WHEEL HOUSING LINER	Torn	237.00 FS	*189.20 FS
26	1		*WHEEL HOUSIN GLINER ATTACHMENT PARTS	Not Necessary	44.00 FS	*- FS
27	1		*STONE CHIP GUARD	Necessary	72.00 FS	*57.36 FS
28	1		*ADHESIVE TAPE	Necessary	54.00 FS	*43.04 FS
29	1		*HEADLIGHT MOUNTING - RH	Cracked	117.00 FS	*93.60 FS
30	1		*HEADLIGHT - RH	Cracked	2,316.00 FS	*1,852.80 FS
31	1		*HEADLAMP BRACKET - RH	Cracked	105.00 FS	*83.60 FS
32	1		*HEADLIGHT RETAINING PLATE - RH	Not Necessary	24.00 FS	*- FS
33	1		*DAY DRIVING LIGHTS POWER MODULE	Not Necessary	538.00 FS	*- FS
34	1		*GAS DISCHARGE LAMP	Not Necessary	408.00 FS	*- FS
35	1		*GAS DISCHARGE LAMP CONTROL UNIT	Not Necessary	1,084.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*HEADLIGHT HOSE - RH	Not Necessary	36.00 FS	*- FS
37	1		*HALOGEN FOG LAMP - RH	Not Necessary	259.00 FS	*- FS
38	1		*LIFT CYLINDER - RH	Damaged	208.00 FS	*166.00 FS
39	1		*LIFT CYLINDER HOSE	Not Necessary	175.00 FS	*- FS
40	1		*FRONT ALUMINIUM RIM - RH	Cut	715.00 FS	*572.00 FS
41	1		*RADIAL TYRE	Not Necessary	1,021.00 FS	*- FS
42	1		*LOCK CARRIER	Not Necessary	1,004.00 FS	*- FS
43	1		*LOCK CARRIER BRACE - RH	Not Necessary	45.00 FS	*- FS
44	1		*COOLANT REGULATOR SUPPORT	Not Necessary	38.00 FS	*- FS
45	1		*READY MIX COOLANT	Not Necessary	91.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE - RH	Not Necessary	26.00 FS	*- FS
47	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
48	1		*FRONT WISHBONE LINK - RH	Not Necessary	533.00 FS	*- FS
49	1		*FRONT SUSPENSION GUIDE - RH	Not Necessary	988.00 FS	*- FS
50	2		*FRONT SUSPENSION GUIDE - FRONT / REAR RH	Not Necessary	1,066.00 FS	*- FS
51	1		*WHEEL BEARING HOUSING - RH	Not Necessary	1,123.00 FS	*- FS
52	1		*SWIVEL JOINT	Not Necessary	191.00 FS	*- FS
53	1		*WHEEL HUB	Not Necessary	463.00 FS	*- FS
54	1		*WHEEL BEARING ASSEMBLY	Not Necessary	570.00 FS	*- FS
55	1		*COUPLING ROD	Not Necessary	127.00 FS	*- FS
56	1		*ANTI-ROLL BAR	Not Necessary	419.00 FS	*- FS
57	1		*SUSPENSION FORKS - RH	Not Necessary	235.00 FS	*- FS
58	1		*GAS SHOCK ABSORBER	Not Necessary	301.00 FS	*- FS
59	1		*DRIVE SHAFT - RH	Not Necessary	2,620.00 FS	*- FS
60	1		*STEERING GEAR	Not Necessary	5,826.00 FS	*- FS
61	1		*TRACK ROD	Not Necessary	98.00 FS	*- FS
62	1		*TIE ROD END - RH	Not Necessary	175.00 FS	*- FS
63	1		*SUNDRIES	Necessary	300.00 FS	*23.20 FS
64	1		*HEADLIGHT SOCKET RHS	Damaged	23.60 FS	*23.60 FS
65	1		*AIR INTAKE FILTER	Cracked	274.80 FS	*274.80 FS
66	1		*NOISE INSULATION	Torn	502.00 FS	*502.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **31,742.40** **7,918.24**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To tow vehicle from accident scene.	New	280.00	0.00
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	New	360.00	280.00
3	To remove and transfer rhs headlight control unit and power module.	New	350.00	250.00
4	To remove and reinstall aircon condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	New	1,200.00	0.00
5	To dismantle and renew front bumper, rhs front fender, and rhs headlight. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	New	4,200.00	1,000.00
6	To respray front bumper, bonnet and rhs front fender.	New	3,000.00	1,650.00
7	To renew rhs front rim with tyre. To carry out wheel alignment.	New	280.00	280.00
8	To remove and renew rhs front wheel suspension assy.	New	1,800.00	0.00
9	To carry out pre-wheel alignment.	New	240.00	0.00
10	To carry out pre and post diagnostic check.	New	384.00	384.00
Gross Labour Cost (\$\$)			12,094.00	3,844.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >