

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20009291/R1TF3E2

**Date:** 12/11/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00054232000

**Claimant Vehicle No :** SKQ6480M

**Insured Vehicle No :** GBJ6926M

Date of Loss: 29/08/2020

Nature of Claim: TP

Claim No: SNM20D203129C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ6480M**

Make & Model: VOLKSWAGEN PASSAT, 1.8 ABT (B5) (A)

Engine No: CAXF15161

Reg. Date: 16/12/2014 (Man. Year: 2014)

Chassis No: WVVZZZ3CZFE048455

Colour: Black

Odometer: 170190 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,285.61	1,751.74	1,533.87	46.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	2,120.00	5,200.00	71.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,605.61</b>	<b>3,871.74</b>	<b>6,733.87</b>	<b>63.49</b>
<b>+ GST 7.00/7.00% (S\$)</b>	742.39	271.02	471.37	63.49
<b>Nett Amount (S\$)</b>	<b>11,348.00</b>	<b>4,142.76</b>	<b>7,205.24</b>	<b>63.49</b>

### INSPECTION

Date of Assignment: 01/09/2020

Date Inspected: 02/09/2020 Inspected At: Volkswagen Centre Singapore (HQ)  
247 Alexandra Road  
Singapore 159934

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$735.75 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2020)
<b>Parts:</b>	143	VOLKSWAGEN PASSAT 1.8 ABT (B5) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKQ6480M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER PRIMED	Deformed	1,617.27 FS	*1,617.27 FS
2	1		*SPOILER SATIN BLACK	Not Necessary	350.61 FS	*- FS
3	1		*DECORATIVE MOULDING BRIGH (LHS)	Not Necessary	164.25 FS	*- FS
4	1		*DECORATIVE MOULDING BRIGH (RHS)	Not Necessary	164.25 FS	*- FS
5	1		*GUIDE PIECE (BUMPER BRACKET RHS)	*Check	39.01 FS	*- FS
6	1		*GUIDE PIECE (BUMPER BRACKET LHS)	Not Necessary	39.01 FS	*- FS
7	1		*BUMPER (BUMPER REINFORCEMENT)	*Check	626.16 FS	*- FS
8	1		*ATTACHMENT STRIP	*Check	70.58 FS	*- FS
9	1		*DECORATIVE MOULDING BRIGH (BOOT LID CHROME)	Scratched	134.47 FS	*134.47 FS
10	1		*NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 3,285.61 1,751.74**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR	New	3,360.00	840.00
2	SPRAY PAINTING	New	3,200.00	800.00
3	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
4	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>7,320.00</b>	<b>2,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >