

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20009296/QPA3Q2
Date: 20/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMH2585U	Insured Vehicle No :	SH6744E
Date of Loss:	28/08/2020	Nature of Claim:	TP
		Claim No:	MCT20080440

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2585U		
Make & Model:	TOYOTA VIOS, 1.5 G (A)	Engine No:	2NRX404182
Reg. Date:	17/01/2019 (Man. Year: 2018)	Chassis No:	MR2B23F3001160629
Colour:	Blue	Odometer:	43353 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,871.90	4,338.40	533.50	10.95
Miscellaneous Items	143.44	132.77	10.67	7.44
Labour	1,240.00	930.00	310.00	25.00
Paintwork Labour	1,618.29	1,457.83	160.46	9.92
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,873.63	6,859.00	1,014.63	12.89
Approved Total (Overridden) (S\$)		6,848.00		

(S\$)	7,873.63	6,848.00	1,025.63	13.03
+ GST 7.00/7.00% (S\$)	551.15	479.36	71.79	13.03
Nett Amount (S\$)	8,424.78	7,327.36	1,097.42	13.03
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
Nett Liability (S\$)		8,183.36		

INSPECTION

Date of Assignment:	02/09/2020	Present Location:	Hua Hong Pte Ltd (Sungei Kadut)
Date Inspected:	03/09/2020	Inspected At:	Hua Hong Pte Ltd (Sungei Kadut) 10 Kaki Bukit Avenue 4, #04-63 Premier @ Kaki Bukit Singapore 415874
Estimated Period of Repair:	6.0 days		

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2021)
Parts:	143	TOYOTA VIOS 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH2585U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE TOP RUBBER (WCP)	Necessary	-	*18.00 F
2	1		*GRILLE GARNISH COVER FRONT GRILLE (WCP)	Scratched	-	*55.00 F
3	1		*L/F AIR DUCT (WCP)	Crumpled	-	*45.00 F
4	1		*L/LWR VENT AIR CHANN (WCP)	Cracked	-	*48.00 F
5	1		*L/R LAMP BRACKET (WCP)	Broken	-	*35.00 F
6	1		*REAR BUMPER REINF (WCP)	Bent	-	*125.00 F
7	1		*REAR FENDER SHIELD CLIP (4 PCS)(WCP)	Necessary	-	*10.00 F
8	1		*REAR FENDER INNER SHIELD (LH) (WCP)	Crumpled	-	*45.00 F
9	1		*SET REVERSE SENSOR (WCP)	Shorted	-	*220.00 F
10	1	NA	*BADGE MODEL (WCP)	Serviceable	28.00 F	*- F
11	1	NA	*BONNET (WCP)	Dented	295.00 F	*295.00 F
12	1	NA	*BONNET LOCK (WCP)	Serviceable	55.00 F	*- F
13	1	NA	*BONNET RUBBER (WCP)	Serviceable	18.00 F	*- F
14	1	NA	*BOOTLID (WCP)	Dented	300.00 F	*300.00 F
15	1	NA	*BOOTLID LOCK (WCP)	Jammed	155.00 F	*155.00 F
16	1	NA	*BOOT SEAL (WCP)	Crumpled	85.00 F	*85.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
17	1	NA	*CLIP FASTENING (WCP)	Necessary	15.00 F	*15.00 F
18	1	NA	*CLIP FASTENING (WCP)	Necessary	15.00 F	*15.00 F
19	1	NA	*FRONT BUMPER (WCP)	Crumpled	220.00 F	*220.00 F
20	1	NA	*FRONT BUMPER GRILLE (WCP)	Cracked	165.00 F	*165.00 F
21	1	NA	*FRONT MANUFACT BADGE (WCP)	Necessary	35.00 F	*35.00 F
22	1	NA	*FRT BUMPER REINF (WCP)	Serviceable	135.00 F	*- F
23	1	NA	*FRT GRILLE CENTER (WCP)	Crumpled	45.00 F	*45.00 F
24	1	NA	*GRILLE (WCP)	Crumpled	75.00 F	*75.00 F
25	1	NA	*GRILLE GARNISH COVER (WCP)	Serviceable	55.00 F	*- F
26	1	NA	*L/DAYTIME HEADLAMP (WCP)	Crumpled	178.00 F	*178.00 F
27	1	NA	*L/F BUMPER BRACKET (WCP)	Broken	40.00 F	*40.00 F
28	1	NA	*L/F HINGE (WCP)	Serviceable	28.00 F	*- F
29	1	NA	*L/RAD GRILLE MLDG (WCP)	Serviceable	38.00 F	*- F
30	1	NA	*L/R BUMPER BRACKET (WCP)	Broken	65.00 F	*65.00 F
31	1	NA	*L/R LAMP ASSY (WCP)	Serviceable	185.00 F	*- F
32	1	NA	*L/R OUT BUMPER BRKT (WCP)	Serviceable	65.00 F	*- F
33	1	NA	*L/R REFLECTOR (WCP)	Scratched	120.00 F	*120.00 F
34	1	NA	*LEFT HEADLAMP ASSY (WCP)	Scratched	320.00 F	*320.00 F
35	1	NA	*LOCK CARRIER STRUT (WCP)	Bent	65.00 F	*65.00 F
36	1	NA	*R/DAYTIME HEADLAMP (WCP)	Serviceable	178.00 F	*- F
37	1	NA	*R/F BUMPER BRACKET (WCP)	Broken	40.00 F	*40.00 F
38	1	NA	*R/F HINGE (WCP)	Serviceable	28.00 F	*- F
39	1	NA	*R/RAD GRILLE MLDG (WCP)	Serviceable	38.00 F	*- F
40	1	NA	*R/R BUMPER BRACKET (WCP)	Broken	65.00 F	*65.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1	NA	*R/R OUT BUMPER BRKT (WCP)	Serviceable	65.00 F	*- F
42	1	NA	*R/R REFLECTOR (NPA)(WCP)	Serviceable	0.00 F	*- F
43	1	NA	*RAD TOP GARNISH (WCP)	Deformed	75.00 F	*15.00 F
44	1	NA	*REAR BOOT LAMP (WCP)	Scratched	155.00 F	*155.00 F
45	1	NA	*REAR BUMPER (WCP)	Crumpled	200.00 F	*200.00 F
46	1	NA	*REAR BUMPER REINF (NPA)(WCP)	Serviceable	0.00 F	*- F
47	1	NA	*REAR MANUFACT BADGE (WCP)	Necessary	35.00 F	*35.00 F
48	1	NA	*REAR PANEL (WCP)	Crumpled	295.00 F	*295.00 F
49	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Cracked	320.00 F	*320.00 F
50	1	NA	*RR LUGG COMPART TRIM (WCP)	Serviceable	110.00 F	*- F
51	1	NA	*RR MANUFACTURE BADGE (WCP)	Necessary	25.00 F	*25.00 F
						F=Franchise part.
					Sub Total (\$\$)	4,429.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	442.90
					Total Parts (\$\$)	4,871.90

3,944.00

394.40

4,338.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NO PLATE (NECESSARY)	35.00	35.00
2	1	SUNDRY (NECESSARY)	97.44	86.77
3	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$)			143.44	132.77

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	1,205.00	1,055.00
2	Total Paint Materials	New	413.29	402.83
Labour Items				
3	Total Panel/Mechanical Labour	New	1,240.00	930.00
Gross Labour Cost (\$)			2,858.29	2,387.83

Report was unsubmitted during this print-out.

< END OF ESTIMATES >