

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009300/URS3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070103029
Claimant Vehicle No :	SLZ7337D	Insured Vehicle No :	SMT6575J
Date of Loss:	29/08/2020	Nature of Claim:	TP
		Claim No:	6422618854SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ7337D	Engine No:	2ZR8353968
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102102016
Reg. Date:	10/04/2018 (Man. Year: 2018)	Odometer:	61530 km
Colour:	Green		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,019.12	4,472.39	5,546.73	55.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,660.00	820.00	33.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,499.12	6,132.39	6,366.73	50.94
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	12,499.12	4,900.00	7,599.12	60.80
+ GST 7.00/7.00% (S\$)	874.94	343.00	531.94	60.80
Nett Amount (S\$)	13,374.06	5,243.00	8,131.06	60.80
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
(S\$)		5,563.00		
Liabe Amount (50.00%) (S\$)		2,781.50		

INSPECTION

Date of Assignment:	02/09/2020	Automobile Integrated Management Pte Ltd (HQ)
Date Inspected:	02/09/2020 Inspected At:	23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
Estimated Period of Repair:	4.0 days	Singapore 415933

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Dented / Bent	1,582.60 FL	*1,582.60 FL
2	1		*FRONT DOOR OUTER GARNISH	Grazed	441.50 FL	*441.50 FL
3	1		*FRONT DOOR OUTER HANDLE	Not Necessary	180.95 FL	*- FL
4	1		*FRONT DOOR INNER LOCK	Not Necessary	541.35 FL	*- FL
5	1		*FRONT DOOR INSULATOR	Not Necessary	141.50 FL	*- FL
6	1		*FRONT DOOR INNER BOARD	Not Necessary	1,055.90 FL	*- FL
7	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	141.60 FL	*- FL
8	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	241.20 FL	*- FL
9	1		*FRONT DOOR W/STRIP	Not Necessary	211.50 FL	*- FL
10	1		*REAR DOOR -RH	Dented / Bent	1,582.60 FL	*1,582.60 FL
11	1		*REAR DOOR OUTER GARNISH	Grazed	381.95 FL	*381.95 FL
12	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	141.60 FL	*- FL
13	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	241.20 FL	*- FL
14	1		*REAR DOOR INSULATION	Not Necessary	141.50 FL	*- FL
15	1		*REAR DOOR INNER BOARD	Not Necessary	1,055.90 FL	*- FL
16	1		*REAR DOOR CHECKER	Not Necessary	89.95 FL	*- FL
17	1		*REAR DOOR W/STRIP	Not Necessary	211.50 FL	*- FL
18	1		*REAR FENDER WHEEL ARCH GARNISH	Grazed	441.20 FL	*441.20 FL
19	1		*SET FRONT DOOR OUTER GARNISH CLIP	Necessary	80.00 FS	*30.00 FS
20	1		*SET FRONT DOOR OUTER HANDLE COVER	Not Necessary	150.00 FS	*- FS
21	1		*SET FRONT DOR SEAMING SEAL	Not Necessary	120.00 FS	*- FS
22	1		*SET F/R DOOR VISOR	Necessary	450.00 FS	*80.00 FS
23	1		*SET REAR DOOR OUTER GARNISH CLIP	Necessary	80.00 FS	*40.00 FS
24	1		*SET REAR DOOR SEAMING SEAL	Not Necessary	120.00 FS	*- FS
25	1		*SET SIDE SILL PANEL SKIRT	Grazed	1,200.00 FS	*1,000.00 FS
26	1		*SET BODY COLOUR WRAP STICKER	Not Necessary	1,200.00 FS	*- FS
					Sub Total (\$\$)	12,225.50 5,579.85
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,206.38 1,107.46
					Total Parts (\$\$)	10,019.12 4,472.39

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK F/R DOOR WIRING	New	80.00	0.00
2	TO RESPRAY UNDERCOATING	New	120.00	60.00
3	TO RESPRAY PAINTING AND ETC	New	1,200.00	1,000.00
4	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	1,080.00	600.00
Gross Labour Cost (\$\$)			2,480.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >