

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20009303/AES3Q2

Date:

19/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070005066

Claimant Vehicle No : SME1404G**Insured Vehicle No :**

SMR5854X

Date of Loss: 30/08/2020

Nature of Claim:

TP

Claim No:

4987666936SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SME1404G**

Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)

Engine No:

27491030467469

Reg. Date: 08/12/2015 (Man. Year: 2015)

Chassis No:

WDD2050402R118780

Colour: Black

Odometer:

96594 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size:

225/50 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,584.31	8,170.94	4,413.37	35.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,410.00	2,080.00	59.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,074.31	9,580.94	6,493.37	40.40
Approved Total (Overridden) (S\$)		7,600.00		

Nett Amount (S\$)	16,074.31	7,600.00	8,474.31	52.72
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,036.45		

INSPECTION

Date of Assignment: 02/09/2020

Date Inspected: 02/09/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
 Singapore 417807

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,391.00 FL	*1,391.00 FL
2	1		*FRONT BUMPER SIDE BRACKET RH	Necessary	135.00 FL	*135.00 FL
3	1		*FRONT BUMPER LOWER BRACKET RH	Not Necessary	110.00 FL	*- FL
4	1		*FRONT BUMPER FOGLAMP GARNISH RH	Not Necessary	195.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	855.00 FL	*- FL
6	1		*FRONT HEADLAMP RH	Cracked	3,345.10 FL	*3,059.00 FL
7	1		*FRONT HEADLAMP CONTROL UNIT RH	Not Necessary	571.50 FL	*- FL
8	1		*FRONT SUPPORT PANEL	Not Necessary	740.10 FL	*- FL
9	1		*FRONT FENDER RH	Dented	925.60 FL	*925.60 FL
10	1		*FRONT FENDER INNER SILED RH	Not Necessary	125.00 FL	*- FL
11	1		*FRONT ENGINE LOWER COVER	Not Necessary	211.00 FL	*- FL
12	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	70.00 FS	*- FS
13	1		*ANGLE SENSOR	Damaged	370.00 FS	*250.00 FS
14	1		*SET ANGLE SENSOR RING	Necessary	80.00 FS	*25.00 FS
15	1		*SET FRONT PARKING SENSOR	Not Necessary	350.00 FS	*- FS
16	1		*FRONT RIM RH	Cut	1,674.00 FS	*1,200.00 FS
17	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
18	1		*SET FRONT FENDER CLIPS	Not Necessary	100.00 FS	*- FS
19	1		*FRONT SHOCK ABSORBER LH	Not Necessary	455.60 FL	*- FL
20	1		*FRONT UPPER ARM LH	Bent	211.00 FL	*211.00 FL
21	1		*FRONT WHEEL HUB LH	Damaged	363.00 FL	*363.00 FL
22	1		*FRONT WHEEL HUB BEARING LH	Necessary	203.00 FL	*203.00 FL
23	1		*FRONT CONTROL ARM LH	Bent	169.00 FL	*169.00 FL
24	1		*FRONT LOWER ARM LH	Bent	160.00 FL	*160.00 FL
25	1		*FRONT KNUCKLE ARM	Damaged	790.00 FL	*790.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,679.90	8,911.60
- List Item Discount on L Items 10.00/10.00% (\$)	1,095.59	740.66
Total Parts (\$)	12,584.31	8,170.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,400.00	500.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,000.00	500.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	0.00
5	TO REMOVE AND REPLACE FRONT HEADLAMP BEAM	New	80.00	0.00
6	TO CLEAR FAULT CODE WITH DIAGNOTIC COMPUTER AND RESET TO MERCEDES SPECIICATION	New	250.00	100.00
7	TO CONDUCT WHEEL ALIGNMENT TEST	New	180.00	80.00
8	TO REMOVE & REPLACE UNDERCARRIAGE PART	New	250.00	200.00
Gross Labour Cost (S\$)			3,490.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >