

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Sep 2020 Edit Reg		02 Sep 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: Lau Pei Ching , ID: S7470555C									
Main Claimant: ACCURATE LEASING PTE LTD , Co. Reg. No.: -									
Vehicle Reg. No.: SMP7260G		Date of Loss: 27/08/2020 00:00 - :59 [10 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2901281263SG		Policy/Cover Note No.: 1800083082 (Comprehensive)							
Vehicle Reg. No. (Insured): SMC6468A		Policy No. (Claimant):							
		Excess:							
Repairer: Neo Automotive (HQ) 53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE, 408934 Ubi - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 11/09/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
AIG_SG (03/09/2020): NO TP GIA REPORT									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMP7260G (2901281263SG)**
[SMC6468A]
TP
ACCURATE LEASING PTE LTD
Aug 27 2020 12:00AM
[Lau Pei Ching]
Neo Automotive

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio				View View in Browser	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/09/20 17:52	General View		Load JPG	☒
2	02/09/20 17:52	General View		Load JPG	☒
3	02/09/20 17:52	General View		Load JPG	☒
4	02/09/20 17:52	Odometer Reading		Load JPG	☒
5	02/09/20 17:52	Chassis Number		Load JPG	☒
6	02/09/20 17:52	General View		Load JPG	☒
7	02/09/20 17:52	General View		Load JPG	☒
8	02/09/20 17:52	General View		Load JPG	☒
9	02/09/20 17:52	General View		Load JPG	☒
10	02/09/20 17:52	General View		Load JPG	☒
11	02/09/20 17:52	General View		Load JPG	☒
12	02/09/20 17:52	General View		Load JPG	☒
13	02/09/20 17:52	General View		Load JPG	☒
14	02/09/20 17:52	General View		Load JPG	☒
15	02/09/20 17:52	General View		Load JPG	☒
16	02/09/20 17:52	General View		Load JPG	☒
17	02/09/20 17:52	General View		Load JPG	☒
18	02/09/20 17:52	General View		Load JPG	☒
19	02/09/20 17:52	General View		Load JPG	☒
20	02/09/20 17:52	General View		Load JPG	☒
21	02/09/20 17:52	General View		Load JPG	☒
22	02/09/20 17:52	General View		Load JPG	☒
23	02/09/20 17:52	General View		Load JPG	☒
24	02/09/20 17:52	General View		Load JPG	☒
25	02/09/20 17:52	General View		Load JPG	☒
26	02/09/20 17:52	General View		Load JPG	☒
27	02/09/20 17:52	General View		Load JPG	☒
28	02/09/20 17:52	General View		Load JPG	☒
29	02/09/20 17:52	General View		Load JPG	☒
30	02/09/20 17:52	General View		Load JPG	☒
31	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
32	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
33	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
34	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
35	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
36	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
37	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
38	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
39	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
40	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
42	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
43	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
44	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
45	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
46	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
47	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
48	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
49	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
50	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
51	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
52	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
53	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
54	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
55	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
56	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
57	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
58	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
59	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
60	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
61	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
62	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
63	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
64	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
65	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
66	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
67	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
68	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
69	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
70	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
71	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
72	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
73	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
74	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
75	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
76	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
77	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
78	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
79	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
80	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
81	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
82	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
83	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
84	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
85	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
86	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
87	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
88	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
89	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
90	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
91	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
92	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
93	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
94	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
95	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
96	03/09/20 17:43	Photographs of Damaged Parts		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	03/09/20 12:32	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20009304/ETF3S2**Date:** 07/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800083082
Claimant Vehicle No :	SMP7260G	Insured Vehicle No :	SMC6468A
Date of Loss:	27/08/2020	Nature of Claim:	TP
		Claim No:	2901281263SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7260G	Engine No:	1NZR793480
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Chassis No:	NHP1707175833
Reg. Date:	11/10/2019 (Man. Year: 2019)	Odometer:	57503 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Arivo 5 mm	Rear Left Side:	Arivo 5 mm
Front Right Side:	Arivo 5 mm	Rear Right Side:	Arivo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/09/2020	Neo Automotive (HQ)
Date Inspected:	02/09/2020 Inspected At:	53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE
Estimated Period of Repair:	4.0 days	Singapore 408934

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	0.00 F	*- F
2	1		*REAR RH DOOR GARNISH	Cut	0.00 F	*- F
3	1		*REAR RH DOOR BOARD	Deformed	0.00 F	*- F
4	1		*REAR RH FENDER	Repair	0.00 F	*- F
5	1		*REAR RH FENDER MOULDING	Cut	0.00 F	*- F
6	1		*REAR RH RIM	Cut	0.00 F	*- F
7	1		*REAR RH BEARING	Jammed	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >