Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009311/UDS3Q2

Date: 28/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700026917

Claimant SI N7480K Insured Vehicle No: SIP2819P

Vehicle No: SLN7480K Insured Vehicle No: SJP2819P

Date of Loss: 28/08/2020 Nature of Claim: TP Claim No: 5021198014SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN7480K

 Make & Model:
 HONDA VEZEL HYBRID, 1.5 RS (A)
 Engine No:
 LEB5943163

 Reg. Date:
 16/05/2017 (Man. Year: 2017)
 Chassis No:
 RU31243155

 Colour:
 Red
 Odometer:
 27517 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,159.90	1,116.24	4,043.66	78.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,470.00	760.00	710.00	48.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,629.90	1,876.24	4,753.66	71.70
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	6,629.90	1,500.00	5,129.90	77.38
+ Loss of Use (3.0 x S\$	70.00/day) (S\$)	210.00		
+ Doc/S	earch Fee (S\$)	7.45		
Ne	tt Liability (S\$)	1,717.45		

INSPECTION

Date of Assignment: 02/09/2020

Date Inspected: 02/09/2020 Inspected At: Super-zee Motor Service (HQ)

BLK 14 DEFU LANE 10, #01-402

Singapore 539195

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHAN JIA LE

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	840.80 F	*- FL
2	2		*REAR BUMPER RETAINERS	Not Necessary	82.60 F	*- FL
3	1		*REAR RH TRIM	Repair	289.60 F	*- FL
4	1		*REAR AXLE	Not Necessary	1,845.30 F	*- FL
5	1		*REAR RH WHEEL BEARING	Damaged	361.50 F	*361.50 FL
6	1		*REAR RH SHOCK ABSORBER	Not Necessary	273.20 F	*- FL
7	1		*REAR RH ABSORBER MOUNTING	Not Necessary	71.30 F	*- FL
8	1		*REAR RH ABSORBER DUST COVER	Not Necessary	39.50 F	*- FL
9	1		*REAR RH COIL SPRING	Not Necessary	184.80 F	*- FL
10	1		*REAR RH TYRE RIM	Cut	450.00 FS	*450.00 FS
11	1		*REAR RH TYRE	Serviceable	250.00 FS	*-FS
12	1		*FENDER OUTER PROTECTOR	Cut	471.30 F	*471.30 FL
F=Fra	ınchise	part. S=SpcN	lett. L=ListItemDisc.			
				Sub Total (S\$)	5,159.90	1,282.80
			- List Item Discount on L Ite	ms 0.00/20.00% (S\$)	0.00	166.56
				Total Parts (S\$)	5,159.90	1,116.24
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANELBEAT WHERE NECESSARY	New	550.00	300.00		
2	TO PUTTY ,APPLY PRIMER & SPRAYPAINT AFFECTED PORTION	New	650.00	400.00		
3	TO APPLY RUSTPROOFING ON REPAIRED ,REPLACED PANEL	New	150.00	0.00		
4	COMPUTERISED WHEEL ALIGNMENT	New	120.00	60.00		
	Gross Labou	1,470.00	760.00			
Report was unsubmitted during this print-out.						

< END OF ESTIMATES >