

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

9/9/20
 1st second hand parts only 2 item
 confirmed 1/5 @ 1500 with christina

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

#01-16 FIRST CENTRE BUILDING
SINGAPORE 555856
TEL : 65708087
FAX : 65708086

Work Order: R007373
 7.9.20 15:18

Factory Japan 2020.0.1 : Honda : Vezel Hybrid : RU3

Front : Left

Actual	Before	Specified Range
-0°23'	-0°22'	-1°00' 1°00'
4°48'	4°48'	4°00' 6°00'
0°00'	-0°07'	-0°08' 0°08'
10°59'	10°58'	11°30' 13°30'
10°36'	10°36'	10°30' 14°30'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°21'	-0°22'	-1°00' 1°00'
4°39'	4°39'	4°00' 6°00'
0°00'	0°08'	-0°08' 0°08'
10°38'	10°38'	11°30' 13°30'
10°16'	10°16'	10°30' 14°30'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°02'	0°00'	-0°45' 0°45'
0°09'	0°09'	
0°22'	0°20'	
0°00'	0°01'	-0°16' 0°16'

Rear : Left

Actual	Before	Specified Range
-1°39'	-1°39'	-2°30' -0°30'
0°09'	0°09'	0°00' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°50'	-1°49'	-2°30' -0°30'
-0°15'	-0°15'	0°00' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
0°11'	0°10'	-0°45' 0°45'
-0°06'	-0°06'	0°00' 0°31'
0°12'	0°12'	
0mm	0mm	

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

31 Aug 2020

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

*Not Authorized
Lien 4/5 \$1500
4/5
Take photo after repair
3 days*

THIRD PARTY CLAIM

OWNER NAME : ANG POH LAE
VEHICLE REG NO : SLN 7480 K
DATE OF ACCIDENT : 28 AUG 2018
PLACE OF ACCIDENT : SERANGOON GARDEN WAY/BRIGHTON CRES
INVOLVING VEH NO : SJP2819P

We append herewith our estimate for the repair of Vehicle No SLN7480K as follows:

Materials Required

1 pc	Rear Bumper	<i>✓</i>	S\$ 840.80	<i>X</i>
2 pcs	Rear Bumper Retainers	<i>✓</i>	S\$ 82.60	<i>X</i>
1 pc	Rear RH Trim <i>Trim</i>	<i>✓</i>	S\$ 289.60	<i>X</i>
1 pc	Rear Axle	<i>✓</i>	S\$1,845.30	<i>X</i>
1 pc	Rear RH Wheel Bearing	<i>Damage</i>	S\$ 361.50	<i>✓</i>
1 pc	Rear RH Shock Absorber	<i>✓</i>	S\$ 273.20	<i>X</i>
1 pc	Rear RH Absorber Mounting	<i>✓</i>	S\$ 71.30	<i>X</i>
1 pc	Rear RH Absorber Dust Cover	<i>✓</i>	S\$ 39.50	<i>X</i>
1 pc	Rear RH Coil Spring	<i>✓</i>	S\$ 184.80	<i>X</i>
1 pc	Rear RH Tyre Rim	<i>(u)</i>	S\$ 450.00	<i>SN ✓</i>
1 pc	Rear RH Tyre	<i>SN</i>	S\$ 250.00	<i>SN X</i>
1 pc	RH Sideskirt <i>Side skirt</i>	<i>Side skirt outer protects (u)</i>	S\$ 471.30	<i>✓</i>
			S\$5,159.90	

Labour Charges

To dismantle & replace damaged parts, panelbeat where necessary	S\$ 550.00	<i>300</i>
To putty, apply primer & spraypaint affected portion	S\$ 650.00	<i>400</i>
To apply rustproofing on repaired, replaced panel	<i>✓</i> S\$ 150.00	<i>X</i>
Computerised wheel alignment	S\$ 120.00	<i>60</i>

SUPER-ZEE MOTOR SERVICE

LKK Auto Consultants hence notify the Repairer of the following:
S\$5,629.90
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Business Registration No. 47959700J

*P. 832.80
202
66624*