

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20009312/T1RA3Q2

**Date:** 29/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900161932

**Claimant**  
**Vehicle No :** SHC2588Y **Insured Vehicle No :** EW1388U

Date of Loss: 01/09/2020 Nature of Claim: TP Claim No: 4098299800SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC2588Y</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C02150
Reg. Date:	14/03/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU103079451
Colour:	Blue	Odometer:	189744 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,071.90	464.45	607.45	56.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	550.00	130.00	19.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,751.90</b>	<b>1,014.45</b>	<b>737.45</b>	<b>42.09</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	122.63	71.01	51.62	42.09
<b>Nett Amount (\$\$)</b>	<b>1,874.53</b>	<b>1,085.46</b>	<b>789.07</b>	<b>42.09</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (\$\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$126.47/day) (\$\$)</b>		379.41		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>1,616.87</b>		

### INSPECTION

Date of Assignment: 01/09/2020

Date Inspected: 01/09/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR BUMPER	Repair	458.60 FL	*- FL
2	10		*BUMPER PIECE	Not Necessary	22.00 FL	*- FL
3	1		*GUARD -REAR BUMPER C	Deformed	552.60 FL	*552.60 FL
4	1		*FILLER -REAR BUMPER	Not Necessary	148.40 FL	*- FL
5	1		*HYUNDAI REVERSE SENSOR AS	Not Necessary	135.70 FS	*- FS
6	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,367.30</b>	<b>602.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	295.40	138.15
<b>Total Parts (\$)</b>	<b>1,071.90</b>	<b>464.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	320.00
2	SPRAYPAINT ON AFFECTED AREA	New	250.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>680.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >