

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 03 Sep 2020

Preliminary Advice

Insured Vehicle No	: SJZ3256D		
TP Vehicle No	: SLJ4091R	Accident Date	: 16/08/2020
Make	: TOYOTA HARRIER	Assignment Date	: 02/09/2020
Date of Inspection	: 02/09/2020	Est. Duration of Repair	: 5
Inspection At	: KUM CHEW MOTOR WORKSHOP (160 SIN MING) (HQ) 160 SIN MING DRIVE, #05-08 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,729.56
Revised Amount	:S\$	3,996.74
Check Items (Estimated)	:S\$	1,778.99
Total	:S\$	5,775.73

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- () The above survey was conducted on a 'without prejudice' basis.