

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20009314/KTF3E2  
**Date:** 23/09/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27190947QMY
<b>Claimant Vehicle No :</b> SLJ4091R	<b>Insured Vehicle No :</b>	SJZ3256D
Date of Loss: 16/08/2020	Nature of Claim:	TP Claim No: 627413

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ4091R	Engine No:	3ZRB917887
Make & Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Chassis No:	ZSU600092887
Reg. Date:	08/12/2016 (Man. Year: 2016)	Odometer:	39522 km
Colour:	Metallic Silver		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,949.56	3,255.12	2,694.44	45.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	1,315.00	465.00	26.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,729.56</b>	<b>4,570.12</b>	<b>3,159.44</b>	<b>40.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>(S\$)</b>	7,729.56	3,600.00	4,129.56	53.43
<b>+ GST 7.00/7.00% (S\$)</b>	541.07	252.00	289.07	53.43
<b>Nett Amount (S\$)</b>	<b>8,270.63</b>	<b>3,852.00</b>	<b>4,418.63</b>	<b>53.43</b>

### INSPECTION

Date of Assignment:	02/09/2020	
Date Inspected:	02/09/2020 Inspected At:	Kum Chew Motor Workshop (160 Sin Ming) (HQ) 160 Sin Ming Drive, #05-08 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2020)
<b>Parts:</b>	M1-SUV	TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLJ4091R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Bent	1,409.36 FL	*1,409.36 FL
2	1		*REAR LID INNER GARNISH	Serviceable	488.73 FL	*- FL
3	1		*REAR LID LOCK	Dented	523.88 FL	*435.00 FL
4	1		*REAR LID HANDLE	Serviceable	1,082.93 FL	*- FL
5	1		*REAR LID RUBBER	Serviceable	447.61 FL	*- FL
6	1		*REAR LID TOYOTA EMBLEM	Not Necessary	86.41 FL	*- FL
7	1		*REAR LID HARRIER EMBLEM	Necessary	62.73 FL	*62.73 FL
8	1		*REAR LID EMBLEM	Not Necessary	59.21 FL	*- FL
9	1		*REAR BUMPER	Buckled	1,621.19 FL	*1,343.00 FL
10	1		*REAR BUMPER REFLECTOR	Serviceable	58.74 FL	*- FL
11	1		*REAR BUMPER RETAINER	Serviceable	75.72 FL	*- FL
12	12		*REAR BUMPER CLIPS	Necessary	102.00 FL	*102.00 FL
13	1		*REAR BUMPER SPOILER	Dented / Cut	423.12 FL	*423.12 FL
14	1		*REAR BUMPER SPONGE	Cracked	158.25 FL	*158.25 FL
15	1		*REAR END PANEL	Repair	792.84 FL	*- FL
16	1		*REAR WINDSCREEN INNER SEAL	Necessary	86.70 FL	*86.70 FL
17	1		*SEALANT	Necessary	60.00 FS	*40.00 FS
18	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,819.42</b>	<b>4,260.16</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,869.86	1,005.04
<b>Total Parts (\$\$)</b>	<b>5,949.56</b>	<b>3,255.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PULL, KNOCK ON REAR ACCIDENT PORTION & CHANGE THE ABOVE PARTS	New	650.00	500.00
2	TO SPRAY & PAINT ON REAR ACCIDENT PORTION	New	800.00	600.00
3	TO ANTI-RUST REAR AFFECTED AREAS	New	80.00	30.00
4	TO CHECK WIRING FUNCTION	New	50.00	15.00
5	TO DISMANTLE & REPLACE 1 SET REVERSE SENSOR	New	80.00	50.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>1,780.00</b>	<b>1,315.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >