

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009315/GGA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800102807
Claimant Vehicle No :	FBC7818Y	Insured Vehicle No :	SMD6528E
Date of Loss:	07/07/2020	Nature of Claim:	TP
		Claim No:	3743602895SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC7818Y	Engine No:	5PV024131
Make & Model:	YAMAHA RXZ, 133cc (M)	Chassis No:	PMY5PV10080024131
Reg. Date:	27/06/2008 (Man. Year: 2008)	Odometer:	89307 km
Colour:	Yellow		
Engine Capacity:	133 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90-18	Rear Tyre Size:	80/90-18
Front Left Side:	IRC 5 mm	Rear Left Side:	IRC 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,914.70	1,966.00	948.70	32.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	230.00	1,130.00	83.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,274.70	2,196.00	2,078.70	48.63
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	01/09/2020		
Date Inspected:	01/10/2020	Inspected At:	Mcs Auto (HQ) 1100 Serangoon Rd Singapore 328195
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	120.00 FL	*120.00 FL
2	1		*SET HANDLE BAR BALANCER L/R	N/S Not Necessary / O/S Cut	40.00 FL	*20.00 FL
3	1		*SET HAND GUARD L/R	Not Necessary	80.00 FL	*- FL
4	1		*BRAKE LEVER	Broken	45.00 FL	*45.00 FL
5	1		*CLUTCH LEVER	Not Necessary	45.00 FL	*- FL
6	1		*METER ASSY	Cut	320.00 FL	*320.00 FL
7	1		*FRONT WINDSHIELD	Cracked	120.00 FL	*120.00 FL
8	1		*HEADLAMP COWLING	Cracked	140.00 FL	*140.00 FL
9	1		*FRONT SHIELD	Not Necessary	75.00 FL	*- FL
10	1		*HEADLAMP ASSY	Missing	280.00 FL	*280.00 FL
11	2		*VIEW MIRROR L/R	Cut	90.00 FL	*90.00 FL
12	1		*SET FRONT SIDE COWLING EMBLEM L/R	Not Necessary	58.00 FL	*- FL
13	2		*FRONT FORK TUBE ASSY L/R	Bent	180.00 FL	*180.00 FL
14	2		*FRONT FORK TUBE GUARD L/R	Not Necessary	80.00 FL	*- FL
15	1		*FRONT LOWER STEERING STEM	Bent	230.00 FL	*230.00 FL
16	1		*FRONT WHEEL RIM	Not Necessary	290.00 FL	*- FL
17	1		*FRONT BRAKE DISC	Not Necessary	250.00 FL	*- FL
18	1		*FRONT FENDER	Cracked	90.00 FL	*90.00 FL
19	1		*FRONT FOOTREST RH	Not Necessary	20.00 FL	*- FL
20	1		*FRONT FOOTREST BRACKET RH	Broken	55.00 FL	*55.00 FL
21	1		*REAR FOOTREST RH	Not Necessary	20.00 FL	*- FL
22	1		*REAR FOOTREST BRACKET RH	Not Necessary	55.00 FL	*- FL
23	1		*MIDDLE /REAR COWLING LH	Cut	120.00 FL	*120.00 FL
24	1		*EXHAUST COVER /PROTECTOR	Cut	70.00 FL	*70.00 FL
25	1		*SET FRONT RIM BEARING & OIL SEAL	Not Necessary	55.00 FS	*- FS
26	1		*SET STEERING CONE UPPER /LOWER BEARING	Necessary	68.00 FS	*68.00 FS
27	1		*FRONT NUMBER STICKER	Necessary	20.00 FS	*20.00 FS
28	1		*BODY COWLING STICKER	Necessary	80.00 FS	*80.00 FS
29	2		*FORK OIL SEAL & DUCT COVER L/R	Necessary	76.00 FS	*76.00 FS
30	2		*FORK OIL	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,202.00	2,154.00
- List Item Discount on L Items 10.00/10.00% (\$)	287.30	188.00
Total Parts (\$)	2,914.70	1,966.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICE CHARGE (2 TRIPS)	New	80.00	30.00
2	SRPAY PAINTING	New	450.00	0.00
3	FRONT BODY FRAME ALIGNMENT	New	380.00	0.00
4	REPLACE REALIGN & ADJUST ABOVE DAMAGED PARTS CHECK WIRING RECONNECTION & LIGHTING SYSTEM	New	450.00	200.00
			Gross Labour Cost (\$\$)	230.00
			1,360.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >