



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2008082
INV Date 02/12/2020
Reference CC4/EQI20009319/Upa3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SKV 7029B
Insured Veh. YP 9456D
Claim No. DM20HO01224 / SG
Policy No. DMCPHQ19-004727
Accident Date 19/08/2020
Inspection Date 09/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI20009319/Upa3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Date : 02-12-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 9456D	Veh. Inspected	SKV 7029B
Policy No.	DMCPHQ19-004727	Coverage (\$)	0.00
Claim No.	DM20HO01224 / SG	Excess (\$)	0.00
Assign From	JANICE	Assign Date	01/09/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA 5 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6CW1071G0122423	Colour	BLACK
Odometer	94662	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2020	Inspection Date	09/09/2020
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 7029B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (SN)	TO REPAIR SEE LABOUR	1,108.20	-
1	BRACKET LHS,FRONT BUMPER (SN)	NOT NECESSARY	41.90	-
1	GROMMET,FRONT BUMPER (SN)	NECESSARY	16.20	16.20
1	GROMMET,FRONT BUMPER (SN)	NECESSARY	16.20	16.20
4	RIVET,FRONT BUMPER (SN)	NECESSARY	22.80	22.80
4	RIVET,FRONT BUMPER (SN)	NECESSARY	32.00	32.00
1	COVER LHS,FOGLAMP (SN)	NOT NECESSARY	78.20	-
3	RIVET,GRILLE (SN)	NOT NECESSARY	12.00	-
1	FRONT FENDER LHS (SN)	DENTED	322.40	322.40
1	STAY LHS,FRONT FENDER (SN)	NECESSARY	30.60	30.60
1	MUDGUARD LHS (SN)	NOT NECESSARY	216.30	-
15	FASTENER,MUDGUARD (SN)	NOT NECESSARY	45.00	-
1	HEADLAMP LHS (SN)	BROKEN	1,482.00	1,482.00
3	CLIP,HEADLAMP (SN)	NECESSARY	19.50	19.50
1	RIVET,HEADLAMP (SN)	NECESSARY	3.50	3.50
2	BULB (SN)	NOT NECESSARY	100.00	-
2	BULB,HEAD LAMP (SN)	NOT NECESSARY	100.00	-
2	BULB,YELLOW (SN)	NOT NECESSARY	7.80	-
2	BULB (SN)	NOT NECESSARY	6.00	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			3,760.60	1,965.20
<u>LABOUR</u>				
TO REPLACE FRONT BUMPER AND FRONT FENDER LH.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.			1,650.00	990.00
TO RESPRAY FRONT BUMPER,BONNET AND FRONT FENDER LH.			2,205.00	945.00
TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			250.00	120.00
TO CARRY-OUT BODY CAVITY PRESERVATION.		NOT NECESSARY	250.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			4,705.00	2,235.00
GRAND TOTAL			8,465.60	4,200.20
RECOMMENDED COST OF REPAIRS				4,200.20

Report Ref No. CC4/EQI20009319/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 7029B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 7029B

RE-INSPECTION

