

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009320/UKA3Q2

Date: 16/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070031214

Claimant
Vehicle No : SH3189C **Insured Vehicle No :** SMS6253T

Date of Loss: 28/08/2020 Nature of Claim: TP Claim No: 2854047177SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH3189C**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR6578071

Reg. Date: 13/05/2016 (Man. Year: 2015) Chassis No: ZVW300478528

Colour: Yellow/Black Odometer: 416857 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	839.10	348.67	490.43	58.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	420.00	630.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	1,889.10	768.67	1,120.43	59.31
Approved Total (Overridden) (\$)		600.00		
(\$)	1,889.10	600.00	1,289.10	68.24
+ GST 7.00/7.00% (\$)	132.24	42.00	90.24	68.24
Nett Amount (\$)	2,021.34	642.00	1,379.34	68.24
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 08/09/2020 Inspected At: Tan Lim Motor Pte Ltd (Defu)

1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	437.90 FL	*437.90 FL
2	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	96.10 FL	*- FL
3	6		*REAR BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
4	1		*O/S REAR LAMP (CRACKED)	Not Consistent With The Impact	557.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,118.80	464.90
- List Item Discount on L Items 25.00/25.00% (\$)	279.70	116.23
Total Parts (\$)	839.10	348.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	500.00	200.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	500.00	200.00
Gross Labour Cost (\$\$)			1,050.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >