



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 3256R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER	DISTORTED	569.00	522.23
1	REAR BUMPER SIDE BRACKETS O/S	DENTED	58.00	58.00
1	REAR BUMPER SPONGE	TORN	168.00	168.00
1	REAR BUMPER ARM SUB ASSY	NOT NECESSARY	84.00	-
1	REAR BUMPER REFLECTOR	CRACKED	49.80	49.80
6	REAR BUMPER CLIP @\$4.00	NECESSARY	24.00	24.00
1	REAR PANEL INNER TRIM GARNISH	TWISTED	268.00	268.00
5	REAR PANEL INNER TRIM GARNISH CLIPS @\$4.00	NOT NECESSARY	20.00	-
1	REAR END PANEL	DENTED	559.00	559.00
	LESS 25% DISCOUNT		-	-412.26
			1,799.80	1,236.77
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	SHORTED	300.00	200.00
			300.00	200.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING.		650.00	600.00
	RE-SPRAYING WORK ON ACCIDENT AFFECTED PARTS.		600.00	600.00
			1,250.00	1,200.00
	GRAND TOTAL		3,349.80	2,636.77
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CS/FCI20009321/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.