

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20009322/UBS3Q2

**Date:** 07/12/2020

### REFERENCE

|                                                         |                             |                       |
|---------------------------------------------------------|-----------------------------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No:                  | MCOM0015              |
| <b>Claimant</b>                                         |                             |                       |
| <b>Vehicle No :</b> SGY8017K                            | <b>Insured Vehicle No :</b> | SHA4014J              |
| Date of Loss: 29/08/2020                                | Nature of Claim: TP         | Claim No: MCT20080503 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                  |
|-----------------------------|-----------------------------------|-------------|------------------|
| Reg No:                     | <b>SGY8017K</b>                   |             |                  |
| Make & Model:               | HONDA CIVIC, 1.6 L VTI (A)        | Engine No:  | R16A12003270     |
| Reg. Date:                  | 09/10/2007 (Man. Year: 2007)      | Chassis No: | JHMF46207S201339 |
| Colour:                     | White                             | Odometer:   | 0 km             |
| Engine Capacity:            | 1595 cc                           |             |                  |
| Market Value/New Car Price: | N/A                               |             |                  |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                  |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/45 R17    | Rear Tyre Size:  | 225/45 R17    |
| Front Left Side:  | Goodyear 6 mm | Rear Left Side:  | Goodyear 6 mm |
| Front Right Side: | Goodyear 6 mm | Rear Right Side: | Goodyear 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 37,679.00         | 3,229.72          | 34,449.28         | 91.43         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 8,200.00          | 1,580.00          | 6,620.00          | 80.73         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>             | <b>45,879.00</b>  | <b>4,809.72</b>   | <b>41,069.28</b>  | <b>89.52</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>        |                   | <b>3,800.00</b>   |                   |               |
| <b>(\$\$)</b>                                    | 45,879.00         | 3,800.00          | 42,079.00         | 91.72         |
| <b>+ GST 7.00/7.00% (\$\$)</b>                   | 3,211.53          | 266.00            | 2,945.53          | 91.72         |
| <b>Nett Amount (\$\$)</b>                        | <b>49,090.53</b>  | <b>4,066.00</b>   | <b>45,024.53</b>  | <b>91.72</b>  |
| <b>+ Car Rental (6.0 x S\$100.00/day) (\$\$)</b> |                   | 600.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                   |                   | 36.49             |                   |               |
| <b>Nett Liability (\$\$)</b>                     |                   | <b>4,702.49</b>   |                   |               |
| <b>Global Sum Settlement (\$\$)</b>              |                   | <b>4,700.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 02/09/2020

Date Inspected: 02/09/2020 Inspected At:

RICO 60 AUTO SERVICES PTE LTD  
(HQ)  
8, KAKI BUKIT AVENUE 4, #02-24,  
PREMIER @ KAKI BUKIT  
Singapore 415875

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                             |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 07 Dec 2020)               |
| <b>Parts:</b>        | 143                                                                                                                                                                          | HONDA CIVIC 1.6 L VTI (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                           |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SGY8017K)                                                                                                                                    |                                                             |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                             |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                             |

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR DOOR (RH)                       | Repair        | 1,379.00 F  | *- FL        |
| 2   | 1   |          | *REAR DOOR LOCK (RH)                  | Not Necessary | 417.00 F    | *- FL        |
| 3   | 1   |          | *REAR DOOR LOCK CATCH(RH)             | Not Necessary | 103.00 F    | *- FL        |
| 4   | 1   |          | *REAR DOOR WINDOW MOULDING (RH)       | Not Necessary | 276.00 F    | *- FL        |
| 5   | 1   |          | *REAR DOOR WINDOW INNER MOULDING (RH) | Not Necessary | 319.00 F    | *- FL        |
| 6   | 1   |          | *REAR DOOR WINDOW GARNISH (RH)        | Not Necessary | 274.00 F    | *- FL        |
| 7   | 1   |          | *REAR DOOR SIDE PROTECTOR (RH)        | Cut           | 416.00 F    | *104.60 FL   |
| 8   | 1   |          | *REAR DOOR INNER BOARD (RH)           | Not Necessary | 677.00 F    | *- FL        |
| 9   | 1   |          | *REAR DOOR INNER BOARD SWITCH (RH)    | Not Necessary | 368.00 F    | *- FL        |
| 10  | 2   |          | *REAR DOOR HINGE UPPER & LOWER (RH)   | Not Necessary | 378.00 F    | *- FL        |
| 11  | 1   |          | *REAR DOOR CHECKER (RH)               | Not Necessary | 209.00 F    | *- FL        |
| 12  | 1   |          | *REAR DOOR WINDOW REGULATOR (RH)      | Not Necessary | 636.00 F    | *- FL        |
| 13  | 1   |          | *REAR DOOR POWER WINDOW MOTOR (RH)    | Not Necessary | 437.00 F    | *- FL        |
| 14  | 1   |          | *REAR DOOR WEATHERSTRIP (RH)          | Not Necessary | 346.00 F    | *- FL        |
| 15  | 1   |          | *REAR DOOR INNER WEATHERSTRIP (RH)    | Not Necessary | 317.00 F    | *- FL        |
| 16  | 1   |          | *ROCKER PANEL (RH)                    | Dented / Bent | 1,679.00 F  | *366.30 FL   |
| 17  | 1   |          | *REAR WINDSCREEN MOULDING             | Not Necessary | 371.00 F    | *- FL        |
| 18  | 1   |          | *REAR FENDER (RH)                     | Repair        | 1,783.00 F  | *- FL        |
| 19  | 1   |          | *REAR FENDER COWLING (RH)             | Not Necessary | 876.00 F    | *- FL        |
| 20  | 1   |          | *TAIL LAMP (RH)                       | Not Necessary | 677.00 F    | *- FL        |
| 21  | 1   |          | *TAIL LAMP PANEL (RH)                 | Not Necessary | 598.00 F    | *- FL        |
| 22  | 1   |          | *REAR BUMPER                          | Cut           | 1,500.00 FS | *1,500.00 FS |
| 23  | 1   |          | *REAR BUMPER RETAINER (RH)            | Not Necessary | 311.00 F    | *- FL        |
| 24  | 1   |          | *REAR ABSORBER (RH)                   | Not Necessary | 399.00 F    | *- FL        |
| 25  | 1   |          | *REAR LOWER ARM (RH)                  | Not Necessary | 376.00 F    | *- FL        |
| 26  | 1   |          | *REAR KNUCKLE (RH)                    |               | 341.00 F    | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                  | Condition     | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------------------|---------------|-------------|------------|
|     |     |          |                                              | Not Necessary |             |            |
| 27  | 1   |          | *REAR KNUCKLE BEARING (RH)                   | Not Necessary | 369.00 F    | *- FL      |
| 28  | 1   |          | *REAR BEARING HUB (RH)                       | Not Necessary | 344.00 F    | *- FL      |
| 29  | 1   |          | *REAR AXLE                                   | No such part  | 1,379.00 F  | *- FL      |
| 30  | 10  |          | *REAR DOOR INNER BOARD CLIPS                 | Not Necessary | 100.00 FS   | *- FS      |
| 31  | 1   |          | *REAR DOOR HANDLE CARBON FIBRE (RH)          | Not Necessary | 800.00 FS   | *- FS      |
| 32  | 1   |          | *REAR DOOR HANDLE END CAP GARNISH FIBRE (RH) | Not Necessary | 300.00 FS   | *- FS      |
| 33  | 1   |          | *ROCKER PANEL SEALANT                        | Not Necessary | 200.00 FS   | *- FS      |
| 34  | 1   |          | *ROCKER PANEL SIDE SKIRT (RH)                | Cut           | 3,500.00 FS | *600.00 FS |
| 35  | 10  |          | *ROCKER PANEL SIDE SKIRT CLIPS               | Necessary     | 100.00 FS   | *35.00 FS  |
| 36  | 1   |          | *REAR WINDSCREEN SEALANT                     | Not Necessary | 200.00 FS   | *- FS      |
| 37  | 1   |          | *REAR FENDER SEALANT                         | Not Necessary | 300.00 FS   | *- FS      |
| 38  | 10  |          | *REAR FENDER COWLING CLIPS                   | Not Necessary | 100.00 FS   | *- FS      |
| 39  | 2   |          | *TAIL LAMP CLIPS                             | Not Necessary | 40.00 FS    | *- FS      |
| 40  | 10  |          | *REAR BUMPER CLIPS                           | Necessary     | 100.00 FS   | *50.00 FS  |
| 41  | 1   |          | *REAR BUMPER LOWER                           | No such part  | 3,000.00 FS | *- FS      |
| 42  | 1   |          | *REAR RIM O/S                                | Cut           | 8,000.00 FS | *600.00 FS |
| 43  | 2   |          | *SET REAR TYRE                               | Serviceable   | 3,000.00 FS | *- FS      |
| 44  | 1   |          | *REAR DOOR SIDE PROTECTOR CHROME (RH)        | Necessary     | 384.00 F    | *85.00 FL  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 37,679.00 3,340.90**  
**- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 111.18**

**Total Parts (\$\$) 37,679.00 3,229.72**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                               | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                           |          |                 |                 |
| 1                               | TO RNR ACCIDENT DAMAGE PARTS ,CUT /WELD ,KNOCK & REALIGN  | New      | 2,700.00        | 600.00          |
| 2                               | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA               | New      | 2,400.00        | 900.00          |
| 3                               | TO RUST PROOF ACCIDENT AFFECTED AREA                      | New      | 800.00          | 0.00            |
| 4                               | TO RNR UPHOLSTERY ,GARNISH AND ATTACHMENT PARTS           | New      | 80.00           | 0.00            |
| 5                               | TO RNR REAR WINDSCREEN                                    | New      | 400.00          | 0.00            |
| 6                               | TO RNR UNDERCARRIAGE SYSTEM                               | New      | 250.00          | 0.00            |
| 7                               | TO CHECK WHEEL ALIGNMENT                                  | New      | 250.00          | 60.00           |
| 8                               | TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION             | New      | 150.00          | 20.00           |
| 9                               | TO RNR TYRE AND WHEEL BALANCING                           | New      | 250.00          | 0.00            |
| 10                              | TO DO DIAGNOSIS AND RESET ,REPROGRAM OR CODING FAULT CODE | New      | 800.00          | 0.00            |
| 11                              | TO DO WATER LEAK TEST                                     | New      | 120.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                           |          | <b>8,200.00</b> | <b>1,580.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >