Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009335/KEA3Q2

Date: 10/02/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700080540 Claimant SHD5932L Insured Vehicle No: SJA575J Vehicle No:

Date of Loss: 31/08/2020 Nature of Claim: TP Claim No: 6141545689SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SHD5932L Reg No:

Engine No: Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) 2ZR2B94959

Reg. Date: 11/01/2019 (Man. Year: 2018) Chassis No: JTDKB3FU603078814

Colour: Metallic Pearl White/Red Odometer: 137053 km

**Engine Capacity:** 1798 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

Yes Footbrake (Serviceable): General Condition: Steering (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm Front Right Side: Rear Right Side: Sailun 9 mm Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,371.10	1,320.25	4,050.85	75.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	485.00	2,885.00	85.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S	8,741.10	1,805.25	6,935.85	79.35
+ GST 7.00/7.00% (S	611.88	126.37	485.51	79.35
Nett Amount (S	9,352.98	1,931.62	7,421.36	79.35
+ Car Rental (3.0 x S\$81.13/day) (S\$)		243.39		
	+ Doc/Search Fee (S\$)	7.49		
Nett Liability (S\$)		2.182.50		

**INSPECTION** 

01/09/2020 Date of Assignment:

Date Inspected: 01/09/2020 Inspected At: Trans-cab Auto Services Pte Ltd

Global Sum Settlement (S\$)

No 2 Ang Mo Kio Street 63

Singapore 569111

2,180.00

Estimated Period of Repair: 2.0 days

Manager: Asher Sng Rong Yi Adjuster: KENNETH KONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	442.60 FL	*442.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	332.70 FL	*332.70 FL
3	1		*REAR BUMPER TOWING COVER	Dented	15.40 FL	*15.40 FL
4	1		*GUARD,REAR BUMPER,CENTER	Dented/Cut	576.30 FL	*576.30 FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*- FL
6	1		*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	*- FL
7	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
8	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL	*- FL
9	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	*- FL
10	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	*- FL
11	1		*REAR BUMPER SIDE RH	Serviceable	123.70 FL	*- FL
12	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
13	1		*COVER,FLOOR UNDER,NO 1	Serviceable	175.10 FL	*- FL
14	1		*COVER,REAR FLOOR	Serviceable	229.90 FL	*- FL
15	1		*REAR COMBINATION LAMP COVER	Serviceable	64.50 FL	*- FL
16	1		*SET PARKING AID	Shorted	700.00 FS	*220.00 FS
17	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	*75.00 FS
18	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*-FS
19	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*-FS
20	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*-FS
21	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*-FS
22	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*-FS
23	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*-FS
24	1		*REAR BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*-FS
25	1		*SET TAILLAMP LOWER CLIP	Not Necessary	40.00 FS	*-FS
26	1		*SET TAILLAMP UPPER CLIP	Not Necessary	40.00 FS	*-FS
27	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	130.00 FS	*-FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)			<b>6,647.00</b> 1,275.90	<b>1,662.00</b> 341.75	
				Total Parts (S\$)	5,371.10	1,320.25
	Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	_abour Items							
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00				
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	220.00				
3	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00				
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00				
5	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,200.00	200.00				
6	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00				
	Gross Labou	r Cost (S\$)	3,370.00	485.00				
	Report was unsubmitted durir	g this print-out.						

< END OF ESTIMATES >