

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009337/AES3Q2

Date: 26/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900141912

Claimant
Vehicle No : SML1974R **Insured Vehicle No :** SMN3099T

Date of Loss: 29/08/2020 Nature of Claim: TP Claim No: 3837593411SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML1974R		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11BA0148
Reg. Date:	09/05/2019 (Man. Year: 2019)	Chassis No:	GF7W0601471
Colour:	Blue	Odometer:	41965 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,551.94	2,304.70	10,247.24	81.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,600.00	1,110.00	4,490.00	80.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	18,151.94	3,414.70	14,737.24	81.19
+ GST 7.00/7.00% (\$\$)	1,270.64	239.03	1,031.61	81.19
Nett Amount (\$\$)	19,422.58	3,653.73	15,768.85	81.19
+ Loss of Use (5.0 x S\$100.00/day) (\$\$)		500.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,161.18		
Global Sum Settlement (\$\$)		4,160.00		

INSPECTION

Date of Assignment: 02/09/2020

Date Inspected: 03/09/2020 Inspected At: Stk Auto (s) Pte Ltd (HQ)
8 kaki bukit ave4, #03-21
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	850.60 FL	*- FL
2	1		*TAILGATE LOGO	Not Necessary	55.00 FL	*- FL
3	1		*TAILGATE LOCK	Not Necessary	450.00 FL	*- FL
4	1		*TAILGATE MOULDING	Not Necessary	446.00 FL	*- FL
5	1		*TAILGATE WEATHERSTRIP	Not Necessary	192.00 FL	*- FL
6	1		*TAILGATE INNER GARNISH	Not Necessary	260.00 FL	*- FL
7	1		*TAILGATE EMBLEM OUTLANDER	Necessary	120.00 FL	*120.00 FL
8	1		*TAILGATE EMBLEM MIVEC	Necessary	65.00 FL	*65.00 FL
9	1		*TAILGATE EMBLEM C&C	Necessary	65.00 FL	*65.00 FL
10	1		*REAR BUMPER	Dented	873.00 FL	*873.00 FL
11	1		*REAR BUMPER RETAINER RH	Broken	25.00 FL	*25.00 FL
12	1		*REAR BUMPER RETAINER LH	Broken	25.00 FL	*25.00 FL
13	1		*REAR BUMPER REFLECTOR RH	Not Necessary	150.00 FL	*- FL
14	1		*REAR BUMPER REFLECTOR LH	Cut	150.00 FL	*150.00 FL
15	1		*REAR BUMPER LOWER CHROME GARNISH	Dented	560.00 FL	*560.00 FL
16	1		*LH REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	1,680.00 FL	*- FL
17	1		*RH REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	1,680.00 FL	*- FL
18	1		*REAR END PANEL	Repair	320.00 FL	*- FL
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	180.00 FL	*- FL
20	1		*LH REAR WHEEL ARCH WHEEL GARNISH	Not Necessary	185.00 FL	*- FL
21	1		*LH REAR FENDER	Not Necessary	1,650.00 FL	*- FL
22	1		*LH TAILLAMP	Not Necessary	565.00 FL	*- FL
23	1		*SMART BUZZLE (NPA)	Broken	0.00 FL	*- FL
24	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
25	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
26	1		*REAR BUMPER REVERSE SENSOR	Shorted	1,500.00 FS	*200.00 FS
27	1		*REAR BUMPER LOWER SPOILER RH	Not Necessary	650.00 FS	*- FS
28	1		*REAR BUMPER LOWER SPOILER LH	Broken	650.00 FS	*380.00 FS
29	1		*REAR END PANEL BRACKET RH	Not Necessary	50.00 FS	*- FS
30	1		*REAR END PANEL BRACKET LH	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,606.60	2,493.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,054.66	188.30
Total Parts (\$\$)	12,551.94	2,304.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	2,500.00	450.00
2	TO SPRAY PAINT ON ACCIDENT AREAS	New	2,500.00	600.00
3	TO REMOVE AND REFIT HEADLAMP WIRING	New	150.00	30.00
4	TO REMOVE AND REFIT FRONT DOOR LH	New	150.00	0.00
5	TO REMOVE AND REFIT REAR DOOR LH	New	150.00	0.00
6	TO RUST PROOFING ACCIDENT AREAS	New	150.00	30.00
Gross Labour Cost (\$)			5,600.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >