

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 08 Sep 2020

## **Preliminary Advice**

|                    |                                                                                                                 |                         |              |
|--------------------|-----------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SJY8405M                                                                                                      |                         |              |
| TP Vehicle No      | : SHC8141M                                                                                                      | Accident Date           | : 01/09/2020 |
| Make               | : HYUNDAI I40                                                                                                   | Assignment Date         | : 02/09/2020 |
| Date of Inspection | : 03/09/2020                                                                                                    | Est. Duration of Repair | : 5          |
| Inspection At      | : BIFROST AUTO PTE LTD (SIN MING) (HQ)<br>BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE<br>SINGAPORE 575644 |                         |              |

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages N/S body portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 16,427.64 |
| Revised Amount              | :S\$ | 10,557.96 |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 10,557.96 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( x ) Lump Sum repair

- ( ) The above survey was conducted on a 'without prejudice' basis.