

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20009344/AGTF3E2

Date: 16/10/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29070321MCX

Claimant Vehicle No : SJK4410Y

Insured Vehicle No : SLL1341D

Date of Loss: 01/09/2020

Nature of Claim: TP

Claim No: 628178

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK4410Y**

Make & Model: MAZDA 5, 2.0 (A)

Engine No: LF10598898

Reg. Date: 21/10/2008 (Man. Year: 2008)

Chassis No: JM6CR10F280307672

Colour: Blue

Odometer: 317966 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17

Rear Tyre Size:

205/50 R17

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,748.56	4,787.36	2,961.20	38.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	1,820.00	2,330.00	56.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,898.56	6,607.36	5,291.20	44.47
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	11,898.56	5,200.00	6,698.56	56.30

INSPECTION

Date of Assignment: 02/09/2020

Date Inspected: 03/09/2020 Inspected At:

Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2020)
Parts:	M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK4410Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REAR LH DOOR BLACK STICKER	Necessary	113.30 FL	*113.30 FL
2	1		*REAR LH DOOR	Distorted	1,072.50 FL	*1,072.50 FL
3	1		*REAR LH DOOR GLASS OUTER MOULDING	Deformed	117.70 FL	*117.70 FL
4	1		*REAR LH DOOR PROTECTOR	Deformed	86.90 FL	*86.90 FL
5	1		*REAR LH DOOR OUTER HANDLE	Damaged	167.20 FL	*167.20 FL
6	1		*REAR LH DOOR TOP HINGE	Not Necessary	71.50 FL	*- FL
7	1		*REAR LH DOOR CENTRE HINGE	Not Necessary	75.90 FL	*- FL
8	1		*REAR LH DOOR LOWER ROLLER BRACKET	Not Necessary	74.80 FL	*- FL
9	1		*REAR LH DOOR LOWER ROLLER	Bent	97.90 FL	*97.90 FL
10	1		*REAR LH DOOR INNER LOCK	Damaged	327.80 FL	*327.80 FL
11	1		*REAR LH DOOR INNER TOP STOPPER	Not Necessary	20.90 FL	*- FL
12	1		*REAR LH DOOR INNER LOWER STOPPER	Not Necessary	25.30 FL	*- FL
13	1		*REAR LH DOOR INNER BOARD	Cracked	748.00 FL	*628.00 FL
14	1		*REAR LH DOOR INNER WEATHER STRIP	Cut	163.90 FL	*163.90 FL
15	1		*REAR LH DOOR POWER WINDOW MOTOR	Not Necessary	215.60 FL	*- FL
16	1		*REAR LH DOOR POWER WINDOW REGULATOR	Damaged	169.40 FL	*169.40 FL
17	1		*REAR BUMPER	Deformed	1,114.30 FL	*986.00 FL
18	1		*REAR BUMPER SIDE HOLDER	Not Necessary	129.80 FL	*- FL
19	1		*REAR LH FENDER	Repair	869.00 FL	*- FL
20	1		*REAR LH FENDER INNER SHIELD	Deformed	31.90 FL	*31.90 FL
21	1		*REAR LH LOWER ARM	Bent	268.60 FL	*268.60 FL
22	1		*REAR LH KNUCKLE ARM	Bent	387.20 FL	*387.20 FL
23	1		*REAR LH KNUCKLE ARM BEARING	Damaged	434.50 FL	*240.90 FL
24	1		*REAR LH SHOCK ABSORBER	Not Necessary	375.10 FL	*- FL
25	1		*LH ROCKER PANEL	Repair	306.90 FL	*- FL
26	1		*LH ROCKER PANEL GARNISH	Deformed	844.80 FL	*625.00 FL
27	1		*REAR LH SPORT RIM	Cut	800.00 FS	*400.00 FS
28	1		*REAR LH TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,410.70	5,884.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,662.14	1,096.84
Total Parts (\$\$)	7,748.56	4,787.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
2	REMOVE & REINSTALL CENTRE DOOR GLASS	New	150.00	30.00
3	REMOVE & REINSTALL ROOF LINING + CUSHION	New	150.00	30.00
4	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
5	REMOVE & REINSTALL REAR LH SUSPENSION	New	400.00	180.00
6	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,600.00	600.00
7	RESPRAY PAINTING	New	1,500.00	800.00
8	TUFF KOTE	New	100.00	50.00
Gross Labour Cost (S\$)			4,150.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >