

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009346/R1ES3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993863
Claimant Vehicle No : SMA874K **Insured Vehicle No :** SLU9850B
 Date of Loss: 30/08/2020 Nature of Claim: TP Claim No: 0375709463SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA874K**
 Make & Model: AUDI A3, 999cc SEDAN TFSI (A) Engine No: CHZ907351
 Reg. Date: 28/05/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V4J1057926
 Colour: White Odometer: 48240 km
 Engine Capacity: 999 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,924.00	6,452.56	3,471.44	34.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,332.00	5,132.00	3,200.00	38.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	18,256.00	11,584.56	6,671.44	36.54
+ GST 7.00/7.00% (\$\$)	1,277.92	810.92	467.00	36.54
Nett Amount (\$\$)	19,533.92	12,395.48	7,138.44	36.54
+ Loss of Use (9.0 x \$60.00/day) (\$\$)		540.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		12,942.93		

INSPECTION

Date of Assignment: 03/09/2020
 Date Inspected: 03/09/2020 Inspected At: Premium Automobiles Pte Ltd - Alexandra (HQ)
 281 Alexandra Pte Ltd, Level B2
 Singapore 159938
 Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,944.00 FS	*1,555.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	32.00 FS	*- FS
4	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	59.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Cut	234.00 FS	*187.20 FS
6	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	82.00 FS	*- FS
7	2		*LED LICENSE PLATE LIGHT	Not Necessary	197.00 FS	*- FS
8	1		*REAR BUMPER SIDE REINFORCEMENT BEAM	Bent	565.00 FS	*451.60 FS
9	1		*REAR BUMPER BRACKET -LH	Not Necessary	27.00 FS	*- FS
10	1		*REAR BUMPER BRACKET -RH	Not Necessary	28.00 FS	*- FS
11	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	66.00 FS	*- FS
12	2		*REAR PARKING AIR SENSOR -INNER /OUTER	Not Working	483.00 FS	*386.40 FS
13	1		*REAR LID	Deformed	2,564.00 FS	*2,051.20 FS
14	1		*REAR LID ATTACHMENT PARTS	Not Necessary	391.00 FS	*- FS
15	2		*REAR LID HINGE -LH/RH	Not Necessary	506.00 FS	*- FS
16	1		*REAR LID FLAP GASKET	Not Necessary	203.00 FS	*- FS
17	1		*REAR LID LOCK STRIKER	Bent	49.00 FS	*39.20 FS
18	1		*REAR LID LOCK	Damaged	184.00 FS	*146.80 FS
19	1		*REAR LID PROTECT CAP	Not Necessary	16.00 FS	*- FS
20	1		*PACKING ADHESIVE	Necessary	18.00 FS	*14.40 FS
21	1		*AUDI EMBLEM	Necessary	122.00 FS	*97.60 FS
22	1		*A3 INSCRIPTION	Necessary	95.00 FS	*75.36 FS
23	1		*TESI INSCRIPTION	Necessary	95.00 FS	*75.36 FS
24	1		*REAR CROSS PANEL TRIM	Not Necessary	153.00 FS	*- FS
25	1		*SUNDRIES	Necessary	250.00 FS	*2.24 FS
26	1		*REAR LID LOCK COVER	Cut	6.00 FS	*6.00 FS
27	1		*REAR END PANELLNG OUTER	Dented	284.40 FS	*284.40 FS
28	1		*REAR END PANELLNG INNER	Dented	579.60 FS	*579.60 FS
29	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
30	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
31	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	9,924.00	6,452.56
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER .REAR BUMPER SPOILER AND REAR LID .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY REAR BUMPER AND REAR LID	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENT	New	480.00	480.00
7	TO CUT OUT AND WELD REAR END PANELLING	New	2,100.00	1,250.00
8	TO RESPRAY REAR END PANELLING	New	900.00	550.00
Gross Labour Cost (\$\$)			8,332.00	5,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >