

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 740X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BENT	561.70	561.70
1	BUMPER LOWER REAR	DENTED / CUT	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH EAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER REFLECTOR RH	CRACKED	16.60	16.60
1	BUMPER BEAM REAR	BENT	547.80	547.80
1	BUMPER BEAM BRACKET RH REAR	BENT	114.50	114.50
1	BOOT REAR	TO REPAIR SEE LABOUR	1,677.20	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT BADGE 'RENAULT'	SERVICEABLE	82.40	-
1	BOOT BADGE	SERVICEABLE	95.80	-
1	TAILLAMP RH	SERVICEABLE	401.40	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	745.80	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	5,263.60	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	125.40	-
	LESS 10% DISCOUNT		-1,114.46	-165.25
			10,030.10	1,487.25
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	75.00	75.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	65.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	65.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	60.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	70.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	75.00	75.00

Report Ref No. CS/AGI20009347/Ktf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	SEAM SEALANT (SN)	NOT NECESSARY	180.00	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	RENAULT TYRE RIM (ROUE 7J 16H) (SN)	SERVICEABLE	385.00	-
1	RENAULT TYRE 215/60/16 (SN)	SERVICEABLE	330.00	-
1	TAILLAMP CLIP (SN)	NOT NECESSARY	40.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	190.00	-
1	SET REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	140.00	-
1	SET END PANEL TRIM CLIP (SN)	NOT NECESSARY	60.00	-
1	EXHAUST MOUNTING (SN)	SERVICEABLE	65.00	-
1	EXHAUST BRACKET REAR (SN)	TO REPAIR SEE LABOUR	60.00	-
			2,720.00	550.00
	<u>LABOUR</u>			
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	220.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BOOT REAR, OUTER PANEL REAR (END PANEL), EXHAUST REAR, EXHAUST CAP REAR AND EXHAUST BRACKET REAR.		1,400.00	200.00
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-

Report Ref No. CS/AGI20009347/Ktf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			5,050.00	495.00
	GRAND TOTAL		17,800.10	2,532.25

RECOMMENDED COST OF LUMP SUM REPAIRS		2,050.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI20009347/Ktf3e2

KONG SENG CHEONG

Report, in whole or in part, does so at his or her own risk.

Licensed Appraiser