

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009357/ARS3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994037

Claimant
Vehicle No : SMS6817S **Insured Vehicle No :** SJV3172H

Date of Loss: 30/08/2020 Nature of Claim: TP Claim No: 9530645566SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS6817S		
Make & Model:	TOYOTA HARRIER, 2.0 PREMIUM CVT (A)	Engine No:	3ZRB884290
Reg. Date:	20/10/2017 (Man. Year: 2016)	Chassis No:	ZSU600089292
Colour:	White	Odometer:	37936 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,697.87	6,181.20	4,516.67	42.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,240.00	1,470.00	54.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,407.87	7,421.20	5,986.67	44.65
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	13,407.87	5,900.00	7,507.87	56.00
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		6,600.00		

INSPECTION

Date of Assignment: 01/09/2020

Date Inspected: 01/09/2020 Inspected At:

Advance Auto Garage (HQ)
23 KAKI BUKIT AVENUE 4 #04-01
AAS KAKI BUKIT CENTRE
Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,450.40 FL	*1,450.40 FL
2	1		*FRONT BUMPER SIDE HOLDER	O/S Necessary	196.20 FL	*98.10 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	490.60 FL	*490.60 FL
4	1		*FRONT BUMPER SPONGE	Cracked	172.00 FL	*172.00 FL
5	1		*FRONT BUMPER FOG LAMP RH	Cracked	359.10 FL	*359.10 FL
6	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	110.10 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Deformed	365.00 FL	*365.00 FL
8	1		*FRONT BUMPER TOW COVER	Missing	38.10 FL	*38.10 FL
9	1		*FRONT BUMPER LOWER DIFFUSER	Deformed	378.10 FL	*378.10 FL
10	1		*HEADLAMP RH	Cracked	3,530.10 FL	*3,530.10 FL
11	1		*HEADLAMP LOWER PANEL	Bent	198.50 FL	*198.50 FL
12	1		*HEADLAMP LOWER PANEL SPONGE	Cracked	112.20 FL	*112.20 FL
13	1		*FRONT GRILLE	Not Necessary	536.10 FL	*- FL
14	1		*FRONT FENDER RH	Buckled	1,090.50 FL	*789.00 FL
15	1		*FRONT FENDER BRACKET RH	Bent	65.40 FL	*65.40 FL
16	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	335.90 FL	*- FL
17	1		*WIPER WASHER TANK	Deformed	155.00 FL	*155.00 FL
18	1		*FRONT WHEEL RIM RH	Not Necessary	2,157.00 FL	*- FL
19	1		*FRONT LOWER ARM RH	Not Necessary	435.10 FL	*- FL
20	1		*FRONT KNUCKLE ARM RH	Not Necessary	577.40 FL	*- FL
21	1		*FRONT SHOCK ABSORBER RH	Not Necessary	591.60 FL	*- FL
22	1		*FRONT WHEEL HUB C/W BEARING RH	Not Necessary	306.10 FL	*- FL
23	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
24	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
25	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
26	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,110.50	8,231.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,412.63	2,050.40
Total Parts (\$\$)	10,697.87	6,181.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING REMOVE AND REFIT PARTS	New	1,000.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	800.00	500.00
3	WIRING CHECK	New	50.00	30.00
4	TUFF COAT	New	150.00	30.00
5	TO PERFORM DIAGNOSTIC TEST	New	150.00	80.00
6	TO REMOVE FRONT UNDERCARRIAGE	New	350.00	0.00
7	TO PERFORM WHEEL ALIGNMENT TEST	New	150.00	0.00
8	TOWING FEES (KING ROLLER)	New	60.00	0.00
Gross Labour Cost (\$\$)			2,710.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >