5/18/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20009360/KPS3Q2

Date:

18/05/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

2100496403 SLJ8814X

Claimant Vehicle No:

SHD9860J 28/08/2020 Insured Vehicle No: Nature of Claim:

TP

Claim No:

6780683898SG

VF1ABL15AUC277376

HIDDEN

713985 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9860J

Make & Model: RENAULT LATITUDE, 2.0 L (A)

01/05/2014 (Man. Year: 2014) Reg. Date:

Colour: Metallic White/Red

Engine Capacity: 1995 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size: 215/60 R16 215/60 R16 Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm Front Right Side: Sailun 9 mm Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		18,248.82	1,197.63	17,051.19	93.44
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,690.00	1,430.00	3,260.00	69.51
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	22,938.82	2,627.63	20,311.19	88.55
	Approved Total (Overridden) (S\$)		2,100.00		

20,838.82 90.85	2,100.00	22,938.82	(\$\$)
1,458.72 90.85	147.00	1,605.72	+ GST 7.00/7.00% (S\$)
22,297.54 90.85	2,247.00	24,544.54	Nett Amount (S\$)
	324.52	+ Car Rental (4.0 x S\$81.13/day) (S\$)	
	7.45	oc/Search Fee (S\$)	+ Do
	2,578.97	Nett Liability (S\$)	

INSPECTION

Date of Assignment: 02/09/2020

Trans-cab Auto Services Pte Ltd (Ang Mo Kio) Date Inspected: Inspected At: 02/09/2020

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
2 1	*DOOR WEATHERSTRIP FRT LH	Serviceable	316.00 FL	*- FL
3 1	*DOOR MOULDING BLACK FRT LH	Not Necessary	100.50 FL	*- FL
4 1	*DOOR MIRROR ASSY LH	Serviceable	1,483.40 FL	*- FL
5 1	*DOOR HANDLE OUTER FRT LH	Serviceable	169.50 FL	*- FL
6 1	*DOOR HINGE UPPER FRT LH	Repair	274.50 FL	*- FL
7 1	*DOOR HINGE LOWER FRT LH	Repair	300.55 FL	*- FL
8 1	*DOOR CHECK FRT LH	Serviceable	90.90 FL	*- FL
9 1	*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
10 1	*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
11 1	*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
12 1	*DOOR SEAL REAR LH	Serviceable	119.80 FL	*- FL
13 1	*DOOR WEATHERSTRIP REAR LH	Serviceable	311.60 FL	*- FL
14 1	*DOOR GLASS RUBBER SEAL REAR LH	Serviceable	320.90 FL	*- FL
15 1	*DOOR HINGE UPPER REAR LH	Repair	241.60 FL	*- FL
16 1	*DOOR HINGE LOWER REAR LH	Repair	169.90 FL	*- FL
17 1	*FENDER PANEL FRT LH	Bent	437.10 FL	*437.10 FL
18 1	*WHEELARCH FRT LH	Serviceable	191.40 FL	*- FL
19 1	*FENDER BRACKET FRT LH	Serviceable	106.40 FL	*- FL
20 1	*HEADLAMP LH	Mtg Cracked	743.60 FL	*743.60 FL
21 1	*BONNET HINGE LH	Repair	236.50 FL	*- FL
22 1	*BONNET	Repair	1,312.70 FL	*- FL
23 1	*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
24 1	*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
25 1	*BUMPER COVER FRT	Repair	747.20 FL	*- FL
26 1	*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
27 1	*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
28 1	*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	*- FL
29 1	*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
30 1	*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
31 1	*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
32 1	*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
33 1	*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
34 1	*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
35 1	*FRONT DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS

5/18/2021

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
36	1	*LH SIDE RENAULT TYRE 215/60/16	Serviceable	330.00 FS	*-FS
37	1	*LH SIDE RENAULT TYRE RIM	Serviceable	380.00 FS	*-FS
38	1	*ROCKER PANEL CLIP	Not Necessary	65.00 FS	*-FS
39	1	*DOOR SEAL CLIP	Not Necessary	65.00 FS	*-FS
40	1	*BUMPER RETAINER CLIP	Not Necessary	60.00 FS	*-FS
41	1	*WHEELARCH CLIP FRT	Not Necessary	60.00 FS	*-FS
42	1	*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	60.00 FS	*-FS
43	1	*SET BUMPER CLIP FRT	Not Necessary	70.00 FS	*-FS
44	1	*SET RADIATOR GRILLE SCREW	Not Necessary	55.00 FS	*-FS
F=Fra	anchise part. S=SpcN	lett. L=ListItemDisc.			
			Sub Total (S\$)	20,120.36	1,315.70
			- List Item Discount on L Items 10.00/10.00% (S\$)	1,871.54	118.07
			Total Parts (S\$)	18,248.82	1,197.63

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,500.00	500.00
5	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,500.00	880.00
7	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
10	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labour Cost (S\$)		4,690.00	1,430.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.